

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 811
9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTOR	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line Section 23 Township 21S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3515' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐ (ORDER R-8541)
	OTHER: Cmt sqzd perf'd, acd / CTI ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-06 to 5-08-89:

POH w/tbg. Cut over Mdl "D" PKR @ 6000'. TOH w/pkr remnants. CO to 6397', tagged prod pkr w/o cmt or sand cap. Set CIBP @ 6320' & cmt ret @ 5999'. Sqzd Tubb perfs 6082' - 6271' w/200 SX Cls "C" cmt + .3% CF-1 followed by 50 SX Cls "C" cmt + 2% CaCl₂. DO cmt ret & cmt + to 6290'. Tagged CIBP @ 6320'. Pres tstd sqz to 500#, held OK. Cut over & rec CIBP. Mld over prod pkr @ 6410'. Dmpd 2 sx cmt on pkr remnants. Washed over prod pkr to 6599'. TOH w/o fish. Jarred on fish @ 6413', rec prod pkr. Also rec pkr ring, 6 jts tbg, 3-6' pmp jts, & 1 bull plug. CO to 6615' (TD). Perf'd Blinebry/Tubb 5665' - 6055' (1 JSPF & 1 JSP2F). Acd Blinebry/Tubb/Drinkard perfs 5665' - 6490' & Drinkard OH 6520' - 6615' w/9240 gals 15% HCl + 2000# rock salt. Installed inj equip, setting Guib Uni-VI PKR @ 5600'. Pres tstd csq to 500# for 30 min, held OK.

6-20-89:

Commenced inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 8-04-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

AUG 28 1989