	CO OIL CONSE CLLANEOUS RI 2 District Offic	EPOF	TS ON	WELI	_ S ີ	(Revis)) le 1106)	C-103 ed 3-55)	
COMPANY Gulf Oil Co	rporation - Bo (Add	<u>c 216</u> ress)	, Hobbs	, New)				
LEASE Nancy Stephens DATE WORK PERFORMED	WELL NO.	2	UNIT	ES	24	T 21-S	R 37-E	<u> </u>
This is a Report of: (Chec	k appropriate b	olock)		Resu	lts of	Test of Ca	sing Shut	 -off
Beginning Drilling Plugging	Operations		-	k	edial W r Rec u	Vork mp leted as	Terry Bli	nebry

Detailed account of work done, nature and quantity of materials used and results obtained.

SEE ATTACHED SHEET

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY Original Well Data: DF Elev. 3414' TD 7150' PBD 7140' Prod. Int. 5675-5750' Compl Date 8-4-54 Tbng. Dia 2-3/8" Tbng Depth 7122' Oil String Dia 5-1/2"Oil String Depth 7149' Perf Interval (s) 7115=70701 and 7060-70281, 7000-69451, 6920-68851 and 5750-56751 Open Hole Interval Producing Formation (s) Line

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	3-26-57	5-15-57
Oil Production, bbls. per day	9	72
Gas Production, Mcf per day	12	361
Water Production, bbls. per day	trase	0
Gas-Oil Ratio, cu. ft. per bbl.	13:33	5014
Gas Well Potential, Mcf per day		

Witnessed by F. J. Grawford	Gulf Oil Corporation			
	(Company)			
OIL CONSERVATION COMMISSION Name	I hereby certify that the information given above is true and complete to the best of my knowledge. Name			
Title	Position Area Supt. of Prod.			
Date	Company Gulf Oil Corporation			

Abandoned Drinkard (il and "ecompleted as Terry Blinebry as follows:

- 1. Pulled rods and pump. Opened upper circulating valve at 3792'. Released from packer and pulled tubing.
- 2. Ran tubing with Baker DR packer plug, set in packer at 6835'.
- 3. Plugged back from 6835-6815' with 20-40 sand. Dumped 3 sacks cement to 6792'. Perforated 5-1/2" casing from 5646-5662', 5778-5794', 5844-5870' and 5884-5895' with 4, 1/2" jet holes per foot.
- Ran 2-7/8" tubing with bridge plug at 5910". Spotted 500 gallons 4. mud acid on perforations in 5-1/2" casing from 5646-5895'. Fulled tubing and bridge plug. Ran 2-7/8" tubing with bridge plug at 5910' and parent packer at 5819'. Spotted 500 gallons mud acid on perforations in 5-1/2" casing from 5844-5895! and squeezed into formation. Treated formation thru perforations in 5-1/2" casing from 5844-5895! with 5000 gallons refined oil with 1# sand per gallon. Spotted 600# crushed mothballs in 24 bbls refineed oil. Treated formation with 5000 gallons refined oil with 1# sand per gallon. Set bridge plug at 58191 and parent packer at 56081. Spotted 500 gallons mud acid on perforations in 5-1/2" casing from 5646-5794' and squeezed into formation. Treated formation thru perforations in 5-1/2" casing from 5646-5794! with 8000 gallons refined oil with 1# sand per gallon. Pumped 500# mothballs in 12 bbls oil. Pumped 500# mothballs in 12 bbls oil. Treated formation thru perforations in 5-1/2" casing from 5646-5794" with 8000 gallons refined oil with 1# sand per gallon.
- 5. Pulled tubing, bridge plug and parent packer. Ran 198 joints 2-3/8" tubing at 58881. Swabbed and well kicked off.