DISTRIBUTION		
	NEW MEXICO OIL CONSERVATION COMMISSION C. C.	Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	The second of th	Effective 1-1-65
U.S.G.S.	10 02 hu	5a. Indicate Type of Lease
LAND OFFICE	**************************************	State Fee
OPERATOR	<del>                                     </del>	5. State Oil & Gas Lease No.
	<del></del>	or did day Louise No.
OO NOT USE THIS FORM USE **A	INDRY NOTICES AND REPORTS ON WELLS OR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. PLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS	1	7. Unit Agreement Name
2. Name of Operator	J OTHER-	8. Farm or Lease Name
Wolfson Oil Company 3. Address of Operator		Shell-Waldrop
3206 Republic	Bank Tower Dallas, Texas	9. Well No.
4. Location of Well	Point 1986. Peaks; 10Aes	1
	//D	10. Field and Pool, or Wildcat
UNIT LETTER		Gouse (Drinkard)
THESouth LINE,	SECTION 6 TOWNSHIP 20S RANGE 395 NMPM	
	15. Elevation (Show whether DF, RT, GR, etc.)	
		12. County
16.	3577 OR	Les (IIIIIIII
NOTICE	ck Appropriate Box To Indicate Nature of Notice, Report or Ot FINTENTION TO: SUBSEQUENT	her Data T REPORT OF:
PERFORM REMEDIAL WORK		
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPN:3.	PLUG AND ABANDONMENT
		<u> </u>
PULL OR ALTER CASING	COMMENCE DRILLING OPN:3.	<u> </u>
OTHER	CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  ODER OTHER  ODER OTHER  ODER OTHER OTHER  ODER OTHER OTHER  ODER OTHER OTHER  ODER OTHER OTHER OTHER  ODER OTHER OTHER	PLUG AND ABANDONMENT
other  17. Describe Proposed or Comple work) SEE RULE 1103.  Work begun 7  9et 25 ax pl  Cut 52 ax casi Set 25 ax casi Set 25 ax plus Set 10ax. plus	CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  ODER OTHER  ODER OTHER  ODER OTHER OTHER  ODER OTHER OTHER  ODER OTHER OTHER  ODER OTHER OTHER OTHER  ODER OTHER OTHER	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Comple work) SEE RULE 1103.  Work begun 7 90: 25 ax pl Cut 52 casi Set 25 ax ce Set 25 ax plus Set 10sx. plus Installed app	change plans  change plans  casing test and cement Job  other  od Operations (Clearly state all pertinent details, and give pertinent dates, including  descriptions from 6900-7100 ft.  light 1000 feet. Pulled casing  ent plug from 1000' to 3900'.  from 3010 to 3110' at intermediate casing.  from surface to 80'.  opriate marker.	estimated date of starting any proposed
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Comple work) SEE RULE 1103.  Work begun 7 90: 25 ax pl Cut 52 casi Set 25 ax ce Set 25 ax plus Set 10sx. plus Installed app	CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  Set Operations (Clearly state all pertinent details, and give pertinent dates, including 8-69.  If from 6900-7100 ft.  If at 1,000 feet. Pulled Casing with plug from 1,000 to 3,900.  If from 3010 to 3110 at intermediate casing.  The surface to 80.  Operate marker.  Note: pumping unit and tank battery have the structure of the pumping unit and tank battery have the surface of the best of my knowledge and belief.	estimated date of starting any proposed
PULL OR ALTER CASING  OTHER  17. Describe Proposed or Comple work) SEE RULE 1103.  Work begun 7  Set 25 ax pl  Cut 52 casi Set 25 ax ce Set 25 ax plus Set 10sx. plus Installed app	CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  Set Operations (Clearly state all pertinent details, and give pertinent dates, including 8-69.  If from 6900-7100 ft.  If at 1,000 feet. Pulled Casing with plug from 1,000 to 3,900.  If from 3010 to 3110 at intermediate casing.  The surface to 80.  Operate marker.  Note: pumping unit and tank battery have the structure of the pumping unit and tank battery have the surface of the best of my knowledge and belief.	estimated date of starting any proposed