

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	X	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico

August 12, 1952

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the **Stanolind Oil and Gas Company**

Minnie Lee Hester Well No. **1** in **N**
(Company or Operator) (Unit)

SE 1/4 **SW** 1/4 of Sec. **6**, T. **20-S**, R. **39-E**, NMPM, **House-San Andres** Pool
(40-acre Subdivision)

Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Production had declined to an average of 10 bbl of oil and 20 bbl of water per day on the above well. Two separate workovers have been performed with no increase in productivity. Production dropped to zero within a month after the completion of the last workover. Sonolog tests reveal that there is no fluid in the hole, indicating that this zone is depleted. It is our intention to plug and abandon this well as follows:

Load hole with mud, shoot off 8-5/8" casing at approximately 370' (indicated top of cement by temperature survey) and pull. Spot 50 sacks cement in bottom of casing and 25 sacks in the 8-5/8" stub. Fill with heavy mud and spot a 20 sack cement plug to surface. A 4" marker will be erected and the location restored to its original contour to conform with Commission regulations.

Approved....., 19.....
Except as follows:

Stanolind Oil and Gas Company
Company or Operator

By: *Ralph L. Hendrickson*

Position: **Field Superintendent**
Send Communications regarding well to:

Approved
OIL CONSERVATION COMMISSION

By: *Roy Yurchough*

Name: **Ralph L. Hendrickson**

Title:

Address: **Box 68, Hobbs, New Mexico**