

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	<input checked="" type="checkbox"/>	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTION TO PLUG WELL	
NOTICE OF INTENTION TO DEEPEN WELL			

Hobbs, New Mexico12-20-35

Place

Date

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico.

Gentlemen:

Following is a notice of intent to do certain work as described below at the

Empire Gas and Fuel Co. State 3 Well No. 3 in NESW 1/4  
 Company or Operator  
 of Sec. 16, T. 21, R. 36, N. M. P. M., Eunice Field,  
Lea County.

## FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

Set 3748 feet of 7 inch casing on 12-20-35. Will test at midnight Sunday 12-22-35. A pressure of 1200 pounds will be applied to casing and drop in pressure noted. If drop in pressure is not too great drilling will be resumed.

Approved \_\_\_\_\_, 19\_\_\_\_  
 except as follows:

OIL CONSERVATION COMMISSION,

By \_\_\_\_\_

Title \_\_\_\_\_

Empire Gas and Fuel Co. (Me.)

Company or Operator

By W. H. HanksPosition District Clerk

Send communications regarding well to

Name D. D. BodieAddress Drawer G.Hobbs, New Mexico

## 201704 20:54:00.000

$$\text{trace}(M^2) = \text{trace}(M^2) + \text{trace}(M^2) + \dots + \text{trace}(M^2) = \text{trace}(M^2) + \text{trace}(M^2) + \dots + \text{trace}(M^2)$$