

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
SHELL WESTERN E&P INC.

3. Address of Operator
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

4. Well Location
Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line
Section 15 Township 21S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3462' GR

WELL API NO.

30-025-09914

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

NORTHEAST DRINKARD UNIT

8. Well No.
602

9. Pool name or Wildcat
NORTH EUNICE BLINEBRY-TUBB-
DRINKARD OIL & GAS

11.

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER: ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Set CIBP, OAP & Acc ☒

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

SUBSEQUENT REPORT OF:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-20-89 to 1-19-90:

Load & PT csg to 500# for 15 min, held. Rel Baker mdl "R" PKR @ 6133' & left swinging. POH w/tbg. CO to 6662' (PBTD). Set CIBP @ 6422'. RIH w/prod string, setting Baker Lok-Set PKR @ 6048'. Swbd well dry. Could not get thru PKR w/perf guns. Dmpd 300 gals xyl dwn tbg to cln tbg. Swbd well dry. Atmptd to run dummy 1-11/16" gun thru PKR. Could not get below PKR. POH w/pkr & tbg. chng out pkr & set Lok-Set @ 6048'. PT csg to 500# for 30 min, held. Swbd well dry. Perf'd Tubb (Gas) 6091' - 6378' (2 JSPP). Acc perfs 6091' - 6401' w/1911 gals 20% HCl + 31.5 tons CO₂. Atmptd to blow well to pit, well dead. SI overnite. Opn well to pit. & well died in abt 2 hrs. Swbd fl to pit. Left flw'g to Texaco gathering system.

2-02 to 2-04-90:

Set frac tank. Left well blowing to pit or tank (slight blow @ end of day). Turned to satellite.

2-22-90: 24-hr tst - 0 oil, 0 wtr, 21 MCF Gas.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. SMITHERMAN

TITLE

REGULATORY SUPV.

DATE

2-23-90

TYPE OR PRINT NAME

J. H. SMITHERMAN

(713) 870-3797

TELEPHONE NO.

(This space for State Use)

APPROVED BY

ORIGINAL SIGNED BY JERRY SEXTON

TITLE

DISTRICT I SUPERVISOR

DATE

FEB 27 1990

CONDITIONS OF APPROVAL, IF ANY: