

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator CAMPBELL & HEDRICK	8. Farm or Lease Name LEE
3. Address of Operator P.O. BOX 401 - MIDLAND, TEXAS 79702	9. Well No. 3
4. Location of Well UNIT LETTER C 800 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 20 TOWNSHIP 21S. RANGE 37E. N.M.P.M.	10. Field and Pool, or Wildcat DRINKARD
15. Elevation (Show whether DF, FT, GR, etc.) 3507 GR.	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER RE-COMPLETION <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 12-17-82 - SET C.I. BRIDGE PLUG AT 6612' GR. TO PLUG-OFF LOWER DRINKARD. TESTED PLUG 1000# FOR 15 MIN.. HELD O.K. PERFORATE 5½" CSG. W/15 .40" HOLES @ 6450', 51, 56, 57, 82, 84, 6563', 65, 80, 81, 85, 89, 92, 6602' & 6604'. RAN SCHLUMBERGER NEUTRON LOG.

2. 12-19-82 - ACIDIZED ABOVE PERFS. 2500 GAL. 15% HCL. USED 24 7/8" BALL SEALERS. DID NOT BALL-OUT. SWABBED BACK ACID.

3. 12-21-82 - SAND FRAC ABOVE PERFS. W/20,000 GAL. UAF 11/3 CARRING 1# PPG 20-40 SD. AVERAGE RATE 18 BBLS./MIN., MAX. PRESSURE 6000#.

4. 3-15-83 - WELL TESTED 2.0 BBLS. OIL, 0 WTR. W/GOR APPROXIMATELY 20,000/1. PUT WELL BACK ON PRODUCTION PRODUCING FROM UPPER DRINKARD PERFS. W/PTTD 6612'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Seay TITLE **PARTNER & PET. ENGR.** DATE **3-24-83**

ORIGINAL SIGNED BY EDDIE SEAY
OIL & GAS INSPECTOR

APPROVED BY _____ TITLE _____ DATE **MAR 30 1983**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 28 1983

**O.C.D.
HOBBS OFFICE**