## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

NOTICE OF INTENTION TO T	EST CASING SHU	T-OFF			NOTICE A	OF INTER	TIO	N TO T WE	SHOOT	distr	X	
NOTICE OF INTENTION TO	CHANGE PLANS		_		NOTICE	#### OF INTEN	TION	TO	PULL OF			
NOTICE OF INTENTION TO REPAIR WELL					OTHERWISE ALTER CASING NOTICE OF INTENTION TO PLUG WELL							
NOTICE OF INTENTION TO DEEPEN WELL					TOTAL OF MILITARY TO THE WHILE							
	Hobbs	, N.	Me X	ζ.	Place	Dec	• ;	23,	1936	Date		
OIL CONSERVATION COMP Santa Fe, New Mexico. Gentlemen:												
Following is a notice of inte						at the				~/.		
Repollo 011 Compe	any	A . Lease		York	•	Well	No	1	i	se/4	of	NE/
of Sec. 20 , T.	<b>21</b> 3 , R.	37.	-	N.	М. Р. М.	•	E	unio	9		Fie	ld,
Lea	Cou	ntv										
To shoot well w/ Daily Production Depth to be shot- Formation to be s	of Oil - 3700 to shot- Lime	N1t1 30 3 3850	rogl Bbl.	LES ANI	1n				ussion			
Daily Production Depth to be shote Formation to be s Inner string of	of Oil - 3700 to shot- Lims	N1t; 30 3 3850	rogl Bbl.	LES ANI .ycer	o regulat <b>1.n</b>				USSION			
Daily Production Depth to be shot- Formation to be s Inner string of	of Oil - 3700 to shot- Lims	N1t; 30 3 3850	rogl Bbl.	LES ANI .ycer	o regulat <b>1.n</b>						To the second se	· ·
Daily Production Depth to be shot- Formation to be s Inner string of c Purpose of shot-	of Oil - 3700 to shot- Lims	30 3 3850 D- g pro 6	rogl 3bl.  Set duct	LES ANI .ycer	n regular		O <u>1</u> ]	L Co		y		a y
Daily Production Depth to be shot- Formation to be s Inner string of c Purpose of shot-	of Oil 3700 to shot- Lime asing 7"0 increase	30 3 3850 D- g pro 6	rogl 3bl.  Set duct	LES ANI .ycer	n regular	CIONS OF	O <u>1</u> ]	L Co	ompa <b>n</b>	y		· ·
Daily Production Depth to be shot- Formation to be s Inner string of c Purpose of shot-	of Oil 3700 to shot- Lime asing 7"0 increase	30 3 3850 D- g pro 6	rogl 3bl.  Set duct	ycer 36 ion	n regular	pollo	<u>О1</u> ]	L Co	mpa <b>n</b>	y		3
Daily Production Depth to be shot- Formation to be s Inner string of c Purpose of shot-	of Oil 3700 to shot- Lime asing 7"0 increase	30 3 3850 D- g pro 6	rogl 3bl.  Set duct	ycer 36 ion	Regular In By A	pollo	O1] Con	L Company	mpan or Opera	tor		3
To shoot well w/ Daily Production Depth to be shot- Formation to be s Inner string of c Purpose of shot-	of Oil 3700 to shot- Lime asing 7"O increase	N1t) 30 3 3850	rogl 3bl.  Set duct	Jes and Jes an	Regular In  Regular Position S	pollo	O1] Coi	L Company Supations	or Opera	tor	to	· 3