

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-09928
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTHEAST DRINKARD UNIT
8. Well No.	801
9. Pool name or Wildcat	NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter D : 660 Feet From The NORTH Line and 660 Feet From The WEST Line Section 22 Township 21S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3434' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: Cmt sqzd, CO, log, OAP & Acd ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-12 to 3-02-90:

POH w/prod equip, CO to 6446' (PBD), Set CICR @ 5975'. Atmptd to sqz Tubb perfs 5996' - 6236' w/150 sx Cls "C" cmt + .3% CF-1 followed by 50 sx Cls "C" cmt + 2% CaCl₂. Dmpd 7 bbls cmt on top of CICR. Tagged @ 5975'. Set pkr @ 5351'. Sqzd Blinebry perfs 5487' - 5926' w/100 sx Cls "C" cmt + .3% CF-1 followed by 100 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & FOH. On 1-18-90, NMOCDS Mr. Jerry Sexton approved method of repairing bradenhead blow. Spot 1 bbl 15% HCl @ 1280'. Perf'd 5-1/2" csg @ 1285'. Set pkr @ 1225'. Estab inj r.t. Rel pkr & FOH. Set CICR @ 1200'. Pmpd 100 sx Thixad cmt followed by 125 sx Cls "C" cmt + 5#/sk gilsonite + 3#/sk salt + .7% CF-1 followed by 100 sx Cls "C" cmt + 2% CaCl₂ + 65 sx Cls "C" Neat cmt. Circ good cmt OUT bradenhead to earth pit. Dmpd 1/2 bbl cmt on top of CICR. Tagged TOC @ 1192'. DO cmt & CICR to 1309', fell free. PT csg to 500# for 15 min, held OK. Tagged TOC @ 5393'. DO cmt to 5929', fell free. Tag

(CONT'D ON REVERSE SIDE.)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 4-6-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 11 1990

@ 5971'. PT csg to 500# for 15 min, held OK. DO CICR @ 5971' & cmt to 6100'. PT csg to 500# for 15 min, held OK. DO cmt to 6242'. DO cmt 6242'-50'. PT csg to 500#, lost 300# in 5 min. Repres csg, lost 320# in 4 min. DO cmt to 6448', fell free & tagged top of fish @ 6450'. RIH w/pkr. Determined perfs from 6150' to 6198' 1K'g. Spot 2 bbls 7% HCl across perfs. POH w/tbg & tools. RIH w/tbg & pkr to 6225'. Spot 13 SX Cls "C" cmt from 6225' to 6100'. POH w/tbg & pkr. DO cmt 6145' - 6215'. Stopped every 10' & FT csg to 500# for 5 min, all tsts held. Mld on Mdl "D" PKr remnants & junk 6450' - 6492'. Mld cmt & junk 6492' - 6589'. Couldn't make further hole. Ran GR/CNL/CCL from 6589' to 5000'. Perf'd Blinbry/Tubb/Drinkard 5710' - 6576' (2 JSPF). Acid perfs 5822' - 6576' w/3990 gals 15% HCl + 750# rock salt. W/RBP set @ 5810' & pkr @ 5691', couldn't estab inj rt. Rel pkr & reset @ 5400'. Pres backside to 500# for 15 min, held OK. Rel pkr & retrieved RBP. Decision made to not sez 1K'g (prev sqzd) perfs. POH w/pkr & RBP. Inst prod equip & ret'd to prod.

RECEIVED

APR 9 1990

OCD
HOBBS OFFICE