

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 913
9. Pool name or Wildcat NORTH EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTOR
2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)
4. Well Location Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The WEST Line Section 23 Township 21S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3410' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Sqzd, OAP, Act & CTI (WFX-579) ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-02 to 2-17-89:
POH w/prod equip. Tagged Fill @ 6575'. Set CIBP @ 6350'. Set pkr @ 5900'. Sqzd Tubb perms 5987' - 6271' w/100 sx CIs "C" cmt + 0.3% CFI followed by 50 sx CIs "C" cmt + 2% CaCl₂. POH w/pkr. DO cmt 5957' - 6182'. Pres tstd sqz to 500#, held OK. Cont drlg cmt to 6270' & CO to 6350'. Pres tstd sqz to 500#, held OK. Perf'd Blinebry & Tubb 5726' - 6069' (1 JSPF & 1 JSP2F). Act perms 5726' - 6069' w/3234 gals 15% HCl-NEFE + 600# rock salt. Knocked out CIBP @ 6350' & pushed to 6573'. Act Drinkard perms 6410' - 47' & OH 6460' - 6573' w/4200 gals 15% HCl-NEFE + 750# rock salt. Installed inj equip, setting Guib Uni-Pkr VI @ 5487'. Pres tstd csq to 500# for 30 min, held OK.

3-17-89: Commenced inj

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>J. H. Smitherman</u>	TITLE <u>PROD. ADMIN. ADVISOR</u>	DATE <u>4-13-89</u>
TYPE OR PRINT NAME <u>J. H. SMITHERMAN</u>	<u>(713) 870-3797</u>	TELEPHONE NO.

(This space for State Use)

APPROVED BY <u>Paul Kautz</u> Geologist	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

APR 18 1989

mp

2041

RECEIVED
APR 17 1989
OCC
HOBBS

RECEIVED

APR 17 1989

OCC
HOBBS