NEW MEXICO STATE LAND OL &E SANTA FE, NEW MEXICO

## DEPARTMENT OF THE STATE GEOLOGIST SANTA FE

## NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr	<b>Garlsbad</b> , N. M 	lex., <b>Harob 1</b> 19 <b>.29</b>
Dear Sir:		
You are hereby notified that it is our inten	tion to abandonStateC	
No in of Sec	of Sec. <b>12</b> , T	<b>21 s</b> , R <b>348</b> ,
N. M. P. M., Wildoat	Oil Field, <b>1.08</b>	County.
We plan to commence work on	Herch 5	19 <b>29</b>

The reasons for wishing to abandon the well are as follows: The hole has been drilled to a total depth of 4194'- and 20'into the so called white crystal productive lime of winkler County without having encountered either eil or gas.

The present condition of the well is as follows:

Casing	Red	ord.	Top of salt 1830'
20" 3.	t at	162'	Base " " 35351
151	н	620'	
12 <del>]</del>	<b>ff</b>	8561	Sulphur water 3880'- 4194'
15 <del>]</del> 12 <del>]</del> 10	11	1564'	-
81	17	3608'	Total depth 4194'
6 5/8	11	3902'	<b>^</b>

The work which we propose to do in abandoning the well is as follows: Fill With Hud to 3904'and set 6 5/8" x 2' wooden dry hole paug at 3902; pull 6 5/8" casing: Fill with mud to 3650, set 84" wooden plug and fill up to 3608' with 20 eacks cement; pull 82 casing: Fill hole with mud & stone to 1600', set 10" wooden plug & fill up to 1564 with 20 sacks edment; pull 10" casing: Fill to 858' with mud & stone & set 124" wooden plug at 856'; pull 124" casing: Fill to 622' with mud & stone & set 151" wooden plug at 620'; pull 154 casing: Fill to surface with mud & stone and cement in piece of 6" casing as permanent marker. Sincerely yours,

Approved ...

Except as follows:

State Geologist or Oil and Gas Inspector.

By D. Boole Company or Operator.

Position District Supit.

Send communications regarding this well to

Name **D. D. Bodie** 

Address Carlsbad New Mexico