NEW MEXICO STATE LAND OFFICE SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST

NEW MEXICO SCHOOL OF MINES SOCORRO, NEW MEXICO

## NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

The reasons for wishing to abandon the well are as follows:

This hole has been drilled to a total depth of 4500 feet without encountering either oil or gas. It is now planned to complete it as a mater well for use in futher development and future operation of the lease by plugging back to 1300 feet

The present condition of the well is as follows:

Anatan menewa

Calling redord: Top of Salt 1925' Sulphur w   20" 62' Base of Salt 3360' 3990'   151 181' Base of Salt 3360' 3990'   121 615' 10' 916' 3990'   81 1630' 6 5/8 38538 55/8	rater
--	-------

The work which we propose to do in abandoning the well is as follows:

Fill hole with mud to 3990' and set 6 5/8" wooden dry hole plug; fill with cement to 3855; test for water shut off; pull 6 5/8" casing: Fill hole with mud to 1975 and set  $8\frac{1}{4}$ " wooden dry hole plug; fill to 1650' with cement; pull  $8\frac{1}{4}$  Casing : Fill hole to 1300' with stone and cement: Leave in ten inch casing and pull 12 $\frac{1}{2}$  and 15 $\frac{1}{2}$  inch if possible.

uly 17 1929

Except as follows:

Sincerely yours,
Empire Gas & Fuel Co.
By
Position
Send communications regarding this well to

Name D. D. Bodio

Address Carlabad New Mexico

•