OIL CONSERVATION COMMISSIO

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

signed and sworn to before a notary public. See additional Indicate nature of re	instructions in the Rules port by checking below.	and Regulations of t	the Commission.	
REPORT ON BEGINNING DRILLING OPERA-	REPORT ON REPA	REPORT ON REPAIRING WELL		
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	REPORT ON PUL	REPORT ON PULLING OR OTHERWISE ALTERING CASING		
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON DEE	PENING WELL		
REPORT ON RESULT OF PLUGGING OF WELL	24-Hour Shut i	n Pressure Tes	t	
Jun	2. 1950 Date		New Mexico	
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO Gentlemen:				
	. T. Mattern	well No. 1 Gas W	ell in the	
Company or Operator SW SE of Sec. 24 Arrowhead Field, Lea			, N. M. P. M.,	
The dates of this work were as follows: Notice of intention to do the work was (was not) subn	nitted on Form C-102 on		19	
and approval of the proposed plan was (was not) obtain DETAILED ACCOUNT OF WORLD	ned. (Cross out incorrect	words.)		

24-hour shut in pressure test - Rule No. 402. Tubing 1060 lbs., casing 1265 lbs.

Witnessed byName		Company		Title	
Subscribed and sworn be	19 6	I hereby swear is true and corr Name	D.G. Dears	ation given above	
اسمرا المنابع المنابع المناب	and the same	Position	Gas Engineer		
	Notary Public	Representing _	Culf Oil Corpora Company or Operator	tion	
My commission expires_	porting 1/2	Address	Hobbs, New Mexic	0	
Remarks:	ROVED		and Ared	Name Name	