SUNDRY NOTICES AND REPORTS ON WELLS  STATE FOR STATE OF THE STATE	NO. OF COPIES RECEIVED		Form C-103
NEW MEXICO OIL CONSERVATION COMMISSION    Substitute   Su	<del></del>		C=102 and C=102
SUBJECT TO		NEW MEXICO OIL CONSERVATION	
SUNDRY NOTICES AND REPORTS ON WELLS  STATE TO GOT LATER THE CONTROL OF THE PROPERTY OF THE PRO			
SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  OF TAKE  OF TAKE  OF TAKE  OF TAKE  OF TAKE  OF TAKE  JAKE L. HANCON  Additions of Community  JAKE L. HANCON  Additions of Community  JAKE L. HANCON  Additions of Community  Dallies, Texas 75221  L. HANCON  State R-8321  SOUTH  THE MEST LIMIT, SECTION 4  TO MAKE L. HANCON  ACCORDANCE OF TAKE  OF			
SUNDRY NOTICES AND REPORTS ON WELLS    SUNDRY NOTICES AND REPORTS ON WELLS   SUNDRY NOTICES AND REPORTS ON WELLS   SUNDRY NOTICES AND REPORTS ON WELLS   SUNDRY NOTICES AND REPORTS ON WELLS   SUNDRY NOTICES AND REPORTS ON WELLS   SUBJECT   SUNDRY NOTICES AND REPORTS ON WELLS   SUBJECT   SUNDRY NOTICES AND REPORTS ON WELLS   SUBJECT   SUNDRY NOTICES AND REPORTS		-	
SUNDRY NOTICES AND REPORTS ON WELLS  OF ALL STATE OF A PROPERTY OF OF A			
The Next Property of Completed Committee Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Set Plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set Plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Straw Zone of Data Not Completed Seven tubing string out of hole.  Seabled well in. Well new producing with Wolfcamp Zone producing through tubing string with Straw Zone plugged off.  Job completed 5-22-65.	SLIN	DEV NOTICES AND DEPORTS ON WELLS	8-8321
The Next Property of Completed Committee Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Set Plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set Plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Straw Zone of Data Not Completed Seven tubing string out of hole.  Seabled well in. Well new producing with Wolfcamp Zone producing through tubing string with Straw Zone plugged off.  Job completed 5-22-65.	OUNT USE THIS FORM FOR USE "APPLI	PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIS	FERENT RESERVOIR.
State B-8321  JAKE L. HANCH  BOX 663 , Dallas, Texas 75221  1. Petrico of Lease Name  Box 663 , Dallas, Texas 75221  1. Petrico of Well  Lattered L. M. Scribban Market DF. RT. CH. Scribban Condition of Well  1. Elevation Show whether DF. RT. CH. Scribban Report of Check Appropriate Box To Indicate Nature of Notice, Report of Other Data  NOTICE OF INTENTION TO:  The West REPORT OF:  Check Appropriate Box To Indicate Nature of Notice, Report of Other Data  NOTICE OF INTENTION TO:  REMEDIAL WORK  COMMAND FRAT AND CHECK STREET AND		( ONE C-101) FOR BUCH PROPOSALS	
JAKE L. HAMON  State E-8321  9. Well No.  1. Consider of Well  1. Consid	OIL GAS WELL WELL	OTHER-	,
Box 663 Dallas, Texas 75221    Control of Well	lame of Operator		8. Farm or Lease Name
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,176.30' in long tubing string. Cut tubing off stram Zone. Opened elsewe at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Journey Lead 10, 176.20 in long tubing string through tubing string with Strawn Zone plugged off.  John works and the information above is true and complete to the best of my knowledge and belief.  Job completed 5-22-65.		HAMON	State E-8321
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  CHARGE PLAND  CHARGE			
Description L 4620    Secretary   South   Sout	·	Texas 75221	1
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PLUS AND ABANDON  CHARGE PLANS  Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.  District Clerk  District Clerk  District Clerk  District Clerk  DATE May 24, 1965			•
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.	UNIT LETTER	1620 FEET FROM THE South LINE AND	560 FEET FROM Osudo (Wolfcamp-Straw
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PLUG AND ABANDON  CHANGE PLANS  CHA	THE West LINE, SE	TION 4 TOWNSHIP 21-S RANG	E 35 *B NMPM.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  SUBSEQUENT REPOR	mmmm	is planning follow that he are on	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  IMPORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  CASINETIZE PLANS CHANT PROCECULAR PARTY  CASINETIZE PLANS CHANT PROCECULAR PARTY  CASINETIZE PLANS CHANT PROCECULAR PARTY  CASINETIZE  CASINETIZ			, etc.) 12. County
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMODIAL WORK  CHANGE PLANS  COMMINETED FIGURE OF THE TEMPORARY Abandon Strawn Zone  CHANGE PLANS  CASING TEST AND CHANGE  PLUS AND CHANGE PLUS AND CHANGE  PLUS AND CHANGE  PLUS AND CHANGE  PLUS AND CHANGE  CASING TEST AND CHANGE  PLUS AND CHANGE  PLUS AND CHANGE  PLUS AND CHANGE  PLUS AND CHANGE  CASING TEST AND CHANGE  CASING TEST AND CHANGE  CASING TEST AND CHANGE  PLUS AND CHANGE  PLUS AND CHANGE  CASING TEST AND CHANGE  CHANGE PLANS  CASING TEST AND CHANGE  CHANGE PLANS  CASING TO			
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawm Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawm Zone plugged off.  Job completed 5-22-65.			Notice, Report or Other Data
COMMENCE OBILLING OPPS.  CHANGE PLANS  CHANG	NOTICE OF	INTENTION TO:	SUBSEQUENT REPORT OF:
COMMENCE ORIGINAL CASING  CHANGE PLANS  CHAN			
CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JOB  OTHER Temporary Abandon Strawn Zone  OTHER Temporary Abandon Strawn Zone  X  CASING TEST AND CEMENT JOB  OTHER Temporary Abandon Strawn Zone  X  CASING TEST AND CEMENT JOB  OTHER Temporary Abandon Strawn Zone  X  CASING TEST AND CEMENT JOB  OTHER Temporary Abandon Strawn Zone  X  CASING TEST AND CEMENT JOB  OTHER Temporary Abandon Strawn Zone  I mark) SEE RULE 1103.  Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.  District Clerk  Date May 24, 1965	$\equiv$	PLUG AND ABANDON REMEDIA:	WORK ALTERING CASING
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.  District Clerk  District Clerk  Date May 24, 1965	<b>=</b>		Too and Abandonwent
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.	ULL OR ALTER CASING		
Learnize Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed north, SEE NULE 1103.  Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  Title District Clerk  DATE May 24, 1965	OTHER	OTHER	emporary Adandon Strawn Zone X
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.			
Set plug in "R" Nipple at 10,176.30' in short tubing string. Cut tubing off at 10,148' and pulled short tubing string out of hole.  Set plug in "R" Nipple at 10,517.05' in long tubing string. This plugged off Strawn Zone. Opened sleeve at 10,480' in long tubing string which opened Wolfcamp Zone into long tubing string.  Swabbed well in. Well new producing with Wolfcamp Zone producing through tubing string with Strawn Zone plugged off.  Job completed 5-22-65.	7. Describe Proposed or Completed	Operations (Clearly state all pertinent details, and giv	e pertinent dates, including estimated date of starting any proposed
TITLE District Clerk  DATE May 24, 1965	10,148' and pulle  Set plug in "R" N  Strawn Zone. Open  Zone into long tu  Swabbed well in.  string with Straw	ipple at 10,517.05' in long tuled sleeve at 10,480' in long to bring string.  Well new producing with Wolfcame Zone plugged off.	ole.  bing string. This plugged off  ubing string which opened Wolfcamp
	I hereby certify that the informat	,	
PROVED DATE	<del></del>		
PROVED TITLE DATE	· / · · · ·		
	PROVED BY	TITLE	DATE

ONDITIONS OF APPROVAL, IF ANY: