

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name New Mexico F State
3. Address of Operator Box 670, Hobbs, New Mexico 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>F</u> <u>1902</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>21-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Osudo Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	
Plugged and Abandoned	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10,351' PB, 10,817' TD.

Pulled rods, pump and tubing. Set CI BP at 10,184' and dumped 2 sacks of cement on top of BF. Shot 5 1/2" casing off at 7422' and pulled casing. Spotted 40 sack cement plug No. 1 from 7489' to 7389' across 5 1/2" casing stub; 40 sack cement plug No. 2 from 6200' to 6100'; 40 sack cement plug No. 3 from 5350' to 5250' in and out of 9-5/8" casing set at 5298'; 20 sack cement plug No. 4 from 50' to surface. Cleaned location and installed dry hole marker. Plugged and abandoned April 8, 1968.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY
C. D. BORLAND

SIGNED _____

TITLE Area Production Manager

DATE April 9, 1968

APPROVED BY John W. Runyan

TITLE _____

DATE _____

ADDITIONS OF APPROVAL, IF ANY: