

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ ☐
5. State Oil & Gas Lease No.
L-4096

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEVALUATE OR TO RACE TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL FORM C-101 FOR PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐
Name of Operator
ERNIE L. HEGWER, INC.
Address of Operator
601 N. Shipp, Hobbs, New Mexico 88240
Location of Well
UNIT LETTER M 760 FEET FROM THE West LINE AND 4542.1 FEET FROM
THE North LINE, SECTION 4 TOWNSHIP 21S RANGE 35E NEPM.

6. Well Name
None
7. Name of Lease
Thomas State
8. Well No.
#1
9. Field and Property or Well No.
Eumont-Yates
10. County
Lea

11. Elevation (Show whether DF, RT, GR, etc.)
3671 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

INFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
LEAK OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set bridge plug at 3912'. Fracture treat perforations from 3864' to 3884' with 30,000 gls. (2% K.C.L. get wtr frac) w/50,000 lbs. sand. Swab load and place on pump. No report as load wtr has not been recovered.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed [Signature] TITLE President DATE 11/6/79

Orig. Signed by
Jerry Sexton
Dist. L. Supv.

APPROVED BY DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 8 1979