

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT INSTRUCTIONS
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. NAME OF OPERATOR Conoco Inc.	3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1650' FWL - Unit Letter K	5. LEASE DESIGNATION AND SERIAL NO. NM-0626640	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. PERMIT AGREEMENT NAME CARL ARELL	8. FARM OR LEASE NAME Lockhart A-30	9. WELL NO. 11	10. FIELD AND POOL, OR WILDCAT Eumet Gates 7 Rves Q	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 30-21S-36E	12. COUNTY OR PARISH Lea	13. STATE NM
14. PERMIT NO. 30-025-21227	15. ELEVATIONS (Show whether DF, RT, GR, etc.)											

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) MURU. Kill well if necessary w/10# per gal mud.
- 2) Run csg scraper to 3850' P.OOH.
- 3) Set CIBP at 3800'. Load csg w/10# per gal mud. Pressure test CIBP to 500 psi for 15 mins. Pump 25 sacks class "C" cement to plug well from 3800' - 3440'. Displace cement w/13 bbls 10# per gal mud & P.OOH.
- 4) Perf at 1800' w/4 jsf & P.OOH.
- 5) G/H w/ 2 3/8" Htg. Establish circ up csg annulus w/10# per gal mud. Pump 450 sacks class "C" cement w/18% salt down 4 1/2" csg to cement 4 1/2" x 7 7/8" annulus & 4 1/2" csg from 1800' to surface & P.OOH w/ Htg. Fill csg to surface w/cement. If cement does not circ, pump 25 sacks down annulus.
- 6) Cut off csg 3' below ground level. Install P&A marker. For further information contact Jay Vashler at 397-5886.

18. I hereby certify that the foregoing is true and correct

SIGNED DAVID F. FINNEY

TITLE Administrative Supervisor

DATE March 6, 1989

(This space for Federal or State office use)

APPROVED BY DAVID F. FINNEY
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 3-9-89

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Cashed (6) Arco (2) Arco (2) Chevron (1) T.C.