

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.E.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ GAS WELL ☐ OTHER-	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 815
4. Location of Well UNIT LETTER G 1750 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE EAST LINE, SECTION 23 TOWNSHIP 21S RANGE 37E NMPM.	10. Field and Pool or Wildcat NORTH EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS
11. Elevation (Show whether DF, RT, GR, etc.) 3397' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER SQZ, OAP & ACDZ ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. POH w/prod equip. Tag PBTD.
2. If tagged short of 6675', CO w/hydrostatic bailer.
3. Set RBP @ 6200' & cap w/2 sx sd. Set pkr @ 5600'.
4. Sqz Blinebry perms 5729' - 5893' w/50 sx CIs "C" cmt + .3% D60 followed by 50 sx CIs "C" cmt + 2% CaCl₂.
5. POH w/pkr.
6. DO cmt & pres tst to 500#.
7. POH w/RBP.
8. Perf Blinebry/Drinkard 5727' - 6660' (1 JSPF).
9. Acdz perms 5727' - 6660' w/11,550 gals 15% HCl-NEA + 2000# rock salt using RBP & pkr.
10. POH w/RBP & pkr.
11. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE 4-29-88

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: