

## O CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company	8. Farm or Lease Name S. J. Sarkeys
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 5
4. Location of Well UNIT LETTER <u>0</u> 1980 FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE, SECTION <u>23</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Tubb Oil&Gas/Wantz Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3382' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Perforate add'l Wantz Abo, Acidize, Commingle DH w/Tubb Oil &amp; Gas</u> <input checked="" type="checkbox"/>	

## 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU 1/8/85. Install BOP & POH w/dual compl assy. POH w/Mod D pkr @ 6680'. RIH w/bit & CO to 7238'. POH w/bit. Ran GR-CNL/CCL. Perf'd add'l Wantz Abo zone w/1 JSPF @ 6735, 38, 44, 75, 81, 6804, 12, 20, 6826, 74, 81, 6918, 42, 47, 48, 49, 50, 51, 52, 69, 6970, 71, 72, 73, 74, 75, 76, 77, 84, 7015, 16, 17, 18, 19, 24, 75, 88, 92, 96, 7108, 10, 7216, 19, 7225' = 44 holes. Set pkr @ 6640'. Acidized perfs 6735-7225' w/7500 gals gelled 15% NEFE acid, flushed to bottom w/gelled BW. On 1/21/85 swbd 7 hrs, rec 6 BNO, 72 BLW, show of gas. On 1/24/85 swbd Abo perfs 6735-7225' 9½ hrs, rec 6 BNO, 48 BW, gas not meas. On 1/28/85 SITP 500#. On 1/28/85 swbd Abo perfs 6735-7225', rec 11 BO, 22 BW, gas not meas. 1/29/85 SITP 300#. On 1/29/85 unlatched from pkr. Equalized tbq & csg. POH w/tbg & pkr. RIH w/2-3/8" OD tbq compl assy, set SN @ 7210'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Elizabeth S. Bush</u>	TITLE <u>Drlg. Engr.</u>	DATE <u>2/5/85</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
FORWARDED BY	TITLE	DATE <u>FEB - 8 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB -7 1985

O.P.D.  
HOLLYWOOD POLICE