Substitute Type of Lease South Substitute Substitu						Form C-103
NEW MEXICO DIL CONSERVATION COMMISSION Construct	DISTRIBUTION					
SUNDRY NOTICES AND REPORTS ON WELLS ODE NOT USE THIS POWN FROM PROPERTY OF STATE AND SERVED AND STATE OF STATE	SANTA FE	NEW ME	XICO OIL CO	DNSERVATIO	N COMMISSION	
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS OF THE SECONDARY OF T	· · · · · · · · · · · · · · · · · · ·	-				
SUNDRY NOTICES AND REPORTS ON WELLS ON NOT USE THIS FORM FOR PROTOSON TO SERVE 3.8 C. S. BACK TO A BUTTON TO SERVE 3.8 C. BACK TO SERVE 3.8 C. S. BACK TO A BUTTON TO SERVE 3.8 C. BACK TO SERV				(t)	1 378	
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS	OPERATOR	-			33	
O'LL GASE OTHER OT						
OIL GRADE ASSESSMENT ABANDON PLUS AND ABANDON PLUS ABANDON PLUS AND ABANDON PLUS AND ABANDON PLUS AND ABANDON PLUS ABANDON PLUS AND ABANDON PLUS AND ABANDON PLUS AND ABANDON PLUS ABANDON PLUS AND ABANDON PLUS AND ABANDON PLUS AND ABANDON PLUS A	SUND (DO NOT USE THIS FORM FOR P USE "APPLIC.	RY NOTICES AND	REPORTS (ON WELLS	FFERENT RESERVOIR.	
The British-American Oil Producing Company The British-American Oil Producing Company Address of Greenter P. O. Box 474 Midland, Texas 2. Location at Well UNIT LETTER P						, , , , , , , , , , , , , , , , , , , ,
Address of Guestater P. O. Box 474 Hidland, Texas 1980 FET FROM THE P 1980 FET FROM P 115. Elevation (Show whether DF, RT, GR, etc.) SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: FEMPORABILY ABANDON CHANGE TAAB CHANGE TAAB OTHER OTHER COMPLETION OTHER COMPLETION TO HELD AND ABANDONMENT TO HELD AND ABANDONMENT THE P 1980 FET FROM THE P 1980 THE P 1980 FET FROM THE P 1980 THE P 1980	2. Name of Operator					
P. O. Box 474 Hidland, Texas 2 Location of Well UNIT LETTER F 1980 FEET FROM THE NORTH THE West Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUS AND ABANDON FEET FROM ABANDON FEET FROM ABANDON FEET FROM THE SUBSEQUENT REPORT OF: REMEDIAL WORK FEED FROM A CHANGE PLANS CHANGE PLANS CHANGE PLANS OTHER Completion THE COMPLET FROM		an Oil Produci	ng Compan	y		North Wilson Deep Unit
The West Line, Section 5 Township 21-S RANGE 35-B NAPPM. Its. Elevation (Show whether DF, RT, GR, etc.) Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERSON REVESIAL WORK STEELENS CHANGE PLANS CHANGE PLANS COMMENCE BRILLING OPHS. CHANGE PLANS CHANGE PLANS COMMENCE BRILLING OPHS. CASING TEST AND CEMENT JOS OTHER COMPLetion Completed Speritions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with 2 JSP7. Cleamed Well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. MCFFD B/MCF Size Press. 2604 23.1 3/64 4025 5590 23.1 20/64 2950	Address of Operator					
UNIT LETTER F 1980 THE West LINE, SECTION 5 TOWNSHIP 21-8 PANGE 35-R NAME. 15. Elevation, Ishow whether DF, RT, GR, etc.) 12. Compy 3647 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PLUG AND ABANDON CHANGE SLANS CHANGE		Midland,	Texas			
THE West LINE, SECTION 5 TOWNSHIP 21-S RANGE 35-B NAME. 15. Elevation (Show whether DF, RT, GR, etc.) 3647 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK COMMENCE DELICING OPES. CHANGE SLANS COMMENCE DELICING OPES. CHANGE SLANS COMPLETION OTHER Completion 7. Describe Proposed or Changests: Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Ran 2" tubing and packer and set packer at 11,226". Perforated Horrow Sand thru tubing from 11,471-78", 11,406-17", 11,380-92", 11,347-52" and 11,320-36" with 2 JSFF. Cleaned well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. Choke Tbg. HCFFD B/HSCF Size Press. 2604 23.1 8/64 4625 4145 23.1 13/64 4025 5590 23.1 20/64 2950		1980	The Nort	hLine and	1980	Indesignated
15. Elevation. (Show whether DF, RT, GR, etc.) 3647 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PULL OR ALTER CASING OTHER COMMENCE DELILING OPHS. CHANGE PLANS OTHER COMPLETION OTHER Completion (Change Plans) CHANGE PLANS OTHER Completion (Change Plans) Change Plans OTHER Completion (Change Plans) (Change Plans)						
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK TEMPORARILY ABANDON OTHER TO LEGISLA WORK COMMENCE ORILLING OPNS. CASING TEST AND CEMENT JOB OTHER TO LEGISLA WORK COMMENCE ORILLING OPNS. CASING TEST AND CEMENT JOB OTHER TO Complete 1103. Ran 2" tubing and packer and set packer at 11,226'. Perforated Horrow Sand thru tubing from 11,471-78', 11,406-17', 11,380-92', 11,347-52' and 11,320-36' with 2 JSFT. Cleaned well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. Choke Tbg. MCFFD B/MCF Size Press. 2604 23.1 8/64 4625 4145 23.1 13/64 4025 5590 23.1 20/64 2950	THE West LINE, SEC	TION 5 TO	жүзнір 2	1-S RANG	35 -8	NMPM.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORARILY ABANDON OTHER TO DESCRIPTION TO CHANGE PLANS OTHER TO MANDE PLANS OTHER		15. Elevati	ion (Show whet	her DF, RT, GI	R, etc.)	12. County
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK TEMPORARILY ABANDON OTHER TO USE THE PROPOSED OF COMPLETE CLEARLY State all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103. Ran 2" tubing and packer and set packer at 11,226". Perforated Morrow Sand thru tubing from 11,471-78", 11,406-17", 11,380-92", 11,347-52" and 11,320-36" with 2 JSFF. Cleaned well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. Choke Tbg. MCFFD B/MCF Size Press. 2604 23.1 8/64 4625 4145 23.1 13/64 4025 5590 23.1 20/64 2950		30	647 GL			Lea
COMMENCE DRILLING OPHS. CHANGE PLANS CHANG	NOTICE OF	INTENTION TO:			SUBSEC	CUENT REPORT OF:
CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Completion Tother Complete Complete Sperations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Ran 2" tubing and packer and set packer at 11,226". Perforated Morrow Sand thru tubing from 11,471-78", 11,406-17", 11,380-92", 11,347-52" and 11,320-36" with 2 JSP7. Cleaned well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. Choke Tbg. MCFPD B/MCF Size Press. 2604 23.1 8/64 4625 4145 23.1 13/64 4025 5590 23.1 20/64 2950	=======================================	PLJG	AND ABANDON L		=	≒
OTHER Completion 7. Leading Proposed or Completes Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Ran 2" tubing and packer and set packer at 11,226". Perforated Horrow Sand thru tubing from 11,471-78", 11,406-17", 11,380-92", 11,347-52" and 11,320-36" with 2 JSP7. Cleaned well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. Choke Tbg. HCPPD B/HCCF Size Press. 2604 23.1 8/64 4625 4145 23.1 13/64 4025 5590 23.1 20/64 2950	=	CHANG	r		DRIECING OPNS.	- PLUG AND ABANDONMENT L
7. Describe Proposed or Completes Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Ran 2" tubing and packer and set packer at 11,226". Perforated Horrow Sand thru tubing from 11,471-78", 11,406-17", 11,380-92", 11,347-52" and 11,320-36" with 2 JSP7. Cleaned well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. Choke Tbg. HCFPD B/HCF Size Press. 2604 23.1 8/64 4625 4145 23.1 13/64 4025 5590 23.1 20/64 2950		CHANG	E PLANS	CASING TE	ST AND CEMENT JOB	i
Ran 2" tubing and packer and set packer at 11,226'. Perforated Morrow Sand thru tubing from 11,471-78', 11,406-17', 11,380-92', 11,347-52' and 11,320-36' with 2 JSPF. Cleaned well up and conducted 4-point test on 2-17-66 as follows: Rate Cond. Choke Tbg. MCFFD B/MSCF Size Press. 2604 23.1 8/64 4625 4145 23.1 13/64 4025 5590 23.1 20/64 2950		CHANG	E □LANS _	_ ,	·-	 a
4145 23.1 13/64 4025 5590 23.1 20/64 2950	отнен			OTHER	Completion	
4145 23.1 13/64 4025 5590 23.1 20/64 2950	oTHER 17. Describe Proposed or Completed work) SEE RULE 1103. Ran 2" tubing and p Perforated Morrow 8 11,320-36' with 2 J	Sperations (Clearly state acker and set p and thru tubing SPF. conducted 4-pe Rate	packer at from 11 point test	details, and given the state of	Completion Tog.	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
5590 23.1 20/64 2950	7. Describe Proposed or Completes work) SEE RULE 1103. Ran 2" tubing and p Perforated Morrow 8 11,320-36' with 2 J	Scher and set pand thru tubing SPF. conducted 4-per Rate	packer at from 11 point test	details, and gis. 11,226'. ,471-78', on 2-17- Choke \$1ze	Completion repertinent dates, in 11,406-17', 66 as follows Tbg. Press.	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
• • • • • • • • • • • • • • • • • • • •	7. Describe Proposed or Completes work) SEE RULE 1103. Ran 2" tubing and p Perforated Morrow 8 11,320-36' with 2 J	acker and set pand thru tubing SPT. conducted 4-per Rate MCFPD	packer at from 11 point test Cond. B/PACF 23.1	details, and given the state of	Completion ce pertinent dates, inc. 11,406-17', 66 as follows Tbg. Press. 4625	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
	7. Describe Proposed or Completes work) SEE RULE 1103. Ran 2" tubing and p Perforated Morrow 8 11,320-36' with 2 J	acker and set pand thru tubing SPF. conducted 4-per Rate MCFPD 2604 4145	packer at g from 11 pint test Cond. B/194CF 23.1 23.1	details, and given the state of	Completion 11,406-17', 66 as follows Tbg. Press. 4625 4025	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
	7. Describe Proposed or Completed work) SEE RULE 1103. Ran 2" tubing and p. Perforated Morrow 8. 11,320-36' with 2 J. Cleaned well up and	scker and set pand thru tubing SPF. conducted 4-per Rate MCFPD 2604 4145 5590 6634	call pertinent packer at g from 11 point test Cond. B/PACF 23.1 23.1 23.1 23.1	details, and gis 11,226'. ,471-78', on 2-17- Choke <u>\$1ze</u> 8/64 13/64 20/64 27/64	Completion 11,406-17', 66 as follows Tbg. Press. 4625 4025	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
onless and order open flow is 7020 regry.	other 17. Describe Proposed or Completes work) SEE RULE 1103. Ran 2" tubing and p Perforated Morrow 8 11,320-36' with 2 J	scker and set pand thru tubing SPF. conducted 4-per Rate MCFPD 2604 4145 5590 6634	call pertinent packer at g from 11 point test Cond. B/PACF 23.1 23.1 23.1 23.1	details, and gis 11,226'. ,471-78', on 2-17- Choke <u>\$1ze</u> 8/64 13/64 20/64 27/64	Completion 11,406-17', 66 as follows Tbg. Press. 4625 4025 2950	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
	7. Describe Proposed or Completed work) SEE RULE 1103. Ran 2" tubing and p. Perforated Horrow 8. 11,320-36' with 2 J. Cleaned well up and Calculated absolute	acker and set pand thru tubing SPF. conducted 4-per Rate MCFPD 2604 4145 5590 6634 open flow is 7	packer at from 11 pint test Cond. B/MCF 23.1 23.1 23.1 23.1	details, and given the state of	Completion 11,406-17', 66 as follows Tbg. Press. 4625 4025 2950 2000	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
	7. Describe Proposed or Completed work) SEE RULE 1103. Ran 2" tubing and p. Perforated Morrow 8. 11,320-36' with 2 J. Cleaned well up and Calculated absolute Ran BHP bomb and sh	acker and set pand thru tubing SPF. conducted 4-per Rate MCFFD 2604 4145 5590 6634 open flow is 7 aut well in for	packer at from 11 pint test Cond. B/PACF 23.1 23.1 23.1 23.1 build-up	details, and given the state of	Completion 11,406-17', 66 as follows Tbg. Press. 4625 4025 2950 2000	cluding estimated date of starting any propose 11,380-92', 11,347-52' and
Ran BHP bomb and shut well in for build-up test on 2-17-66.	7. Describe Proposed or Completes work) SEE RULE 1103. Ran 2" tubing and p. Perforated Morrow 8 11,320-36' with 2 J. Cleaned well up and Calculated absolute Ran BHP bomb and sheet.	acker and set pand thru tubing spr. conducted 4-per Rate MCPPD 2604 4145 5590 6634 open flow is a part of the second seco	packer at g from 11 pint test Cond. B/196CF 23.1 23.1 23.1 23.1 build-up	details, and given the state of my knowless of my k	Completion 11,406-17', 66 as follows Tbg. Press. 4625 4025 2950 2000 2-17-66.	11,380-92', 11,347-52' and
Ran BHP bomb and shut well in for build-up test on 2-17-66. 8.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.	7. Describe Proposed or Completed work) SEE RULE 1103. Ran 2" tubing and p. Perforated Horrow 8 11,320-36' with 2 J. Cleaned well up and Calculated absolute Ran BHP bomb and sheet.	acker and set pand thru tubing spr. conducted 4-per Rate MCPPD 2604 4145 5590 6634 open flow is a part of the second seco	packer at g from 11 pint test Cond. B/196CF 23.1 23.1 23.1 23.1 build-up	details, and given the state of my knowless of my k	Completion 11,406-17', 66 as follows Tbg. Press. 4625 4025 2950 2000 2-17-66.	11,380-92', 11,347-52' and

CONDITIONS OF APPROVAL, IF ANY: