

OF COPIES RECEIVED	
DISTRIBUTION	
TAKE	
E	
G.S.	
NO OFFICE	
CRATOR	

C CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

☒ GAS WELL ☐ OTHER	7. Unit Agreement Name Eunice Monument South Unit
1. Operator Chevron U.S.A. Inc.	8. Form or Lease Name
2. Address of Operator P.O. Box 670 Hobbs, NM 88240	9. Well No. 365
3. Location of Well LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM <u>East</u> LINE, SECTION <u>17</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Whichever Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) <u>3607'</u> GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
WELL ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
ALTER CASING ☐		CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations). SEE RULE 1103.

Clean out to 4060'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

<u>M. E. Ahern</u>	TITLE <u>Staff Drilling Engineer</u>	DATE <u>1-6-1987</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
	TITLE	DATE <u>JAN 8 1987</u>
NAME OF APPROVAL, IF ANY:		

RECEIVED
JAN 7 1987
OCCD
HOBBS OFFICE