

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-21894
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Eunice Monument South Unit
8. Well No. 424
9. Producing or Proposed Eunice Monument Grayburg S.A.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator Chevron USA, Inc.	8. Well No. 424
3. Address of Operator 15 Smith Rd. Midland, Tx 79705	9. Producing or Proposed Eunice Monument Grayburg S.A.
4. Well Location: Unit Letter <u>P</u> <u>760</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>16</u> Township <u>21-S</u> Range <u>36-E</u> NMPM County <u>Lea</u>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set 4 1/2" CIBP @ 3710' (Grayburg-Queen) spot 30sx plug fr/3716' to 3400' Tag @ 3281'
2. Displace hole w/MLF 9.5# Brine w/25# Gel p/BBL
3. Spot 25sx plug fr/2600' to 2400' (B-salt)
4. Perf 4 holes @ 1400', sqz w/75sx fr/1400' to 1100' (8 5/8" shoe, T-salt) Tag @ 1033'
5. Perf 4 holes @ 350' (Fresh wtr zone) sqz w/775sx
6. Bradenhead sqz- Circ cmt between 4 1/2" X 8 5/8" csg & behind 8 5/8" csg w/185sx
7. Circ cmt fr/400' to surf w/35sx Tag @ surf, Install dry hole marker 8-30-02

reported as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Poly Abalos TITLE SUNSET / MANAGER DATE 8/30/02
Type or print name POLY ABALOS Telephone No. 520-8756
(This space for State use)

APPROVED BY GARY W WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE FEB - 7 2003
Conditions of approval, if any:

GWW

Ed Gonzalez fld rep 3-6-03