

U.S. CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER-	7. Unit Agreement Name Eunice Monument South Unit
Name of Operator Chevron U.S.A. Inc.			8. Farm or Lease Name
Address of Operator P.O. Box 670, Hobbs, New Mexico 88240			9. Well No. 282
Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>760</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>8</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.			10. Field and Pool, or Wildcat Eunice Monument G-SA
15. Elevation (Show whether DF, RT, GR, etc.) 3588' DF			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
ILL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cleaned out well to PBTD @ 4010'. PERFORATED FROM 3894-3984'
(20 HOLES). ACIDIZED ^{ALL} PERFS FROM 3793-3986' w/ 2500 GALS
15 % NEFE HCL ACID. TEST Pumped. Ran RBP & SET AT 3884'.
614 w/ PROD. Equip, Return well to PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Division Proration Engineer DATE 7/31/86

ORIGINAL SIGNED BY JERRY SEXTON

MOVED BY DISTRICT SUPERVISOR

TITLE

DATE AUG 4 1986

ADDITIONS OF APPROVAL, IF ANY: