NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.	+- ver 10 0 23 2117	5a. Indicate Type of Lease
LAND OFFICE	 	State X Fee.
OPERATOR		5. State Oil & Gas Lease No. OG 1041

S (DO NOT USE THIS FORM USE "AI	UNDRY NOTICES AND REPORTS ON WELLS FOR PROPOSALS TO DEFILE OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. PULICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
l.		7. Unit Agreement Name
well well 2. Name of Operator	OTHER- DRY HOLE	8. Farm or Lease Name
	RODUCTION CORPORATION	WILSON STATE
3. Address of Operator	ROBOTION GORLOWITZON	9. Well No.
	OSWELL, NEW MEXICO 88201	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER A	. 660 FEET FROM THE North LINE AND 330 FEET FRO	UNDESIGNATED
East	section 30 township 21S RANGE 35E	
THE LAST LINE	, SECTION 30 TOWNSHIP 213 RANGE 391 NMPN	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3668' GR	LEA
16. CI	neck Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
		T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	Γ
	OTHER	
OTHER		
17. Describe Proposed or Compl	eted Operations (Clearly state all pertinent details, and give pertinent dates, includin	g estimated date of starting any proposed
work) SEE RULE 1103.		
5/12/67:	Spotted cement plugs as follows:	
	100' plug @ 3700' - 3800'	
	100' plug @ 3350' - 3450'	
	100' plug @ 1700' - 1800'	
	100' plug @ 85' - 185' 30' plug at surface	
	Drilling mud between plugs. Set dry hole marker	at
	surface and cleaned location.	
18. I hereby certify that the info	rmation above is true and complete to the best of my knowledge and belief.	
- 211-	7.7	
SIGNED // Lee	EXPLORATION MANAGER	DATE 10/6/67
T. LEE	IAR VAR D	
() L	In Russia	
APPROVED BY	W. THE	DATE
CONDITIONS OF APPROVAL,	FANY:	