

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505


WELL API NO. 30-025-22821
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Arrowhead Grayburg Unit
8. Well No. 101
9. Pool name or Wildcat Arrowhead

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Chevron USA, Inc.	
3. Address of Operator 15 Smith Rd. Midland, Tx 79705	
4. Well Location Unit Letter <u>B</u> <u>660</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>East</u> line Section <u>25</u> Township <u>21-S</u> Range <u>36-E</u> NMPM County <u>Lea</u>	
10. Production (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operation. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set 4 1/2" CIBP @ 3625' spot 35sx plug fr/3625' to 3200' (Grayburg-Queen) Tag @ 3158'
2. Displace hole w/MIL F 9.5# Brine w/25# Gel p/BBL
3. Spot 25sx plug fr/2700' to 2500' (Gates-B-salt)
4. Perf 4 holes @ 1362" sqz perf w/125sx fr/1362' to 1100' (8 5/8" shoe, T-salt) Tag @ 1008'
5. Perf 4 holes @ 350' unable to sqz cmt fr/400' to surf w/35sx (Fresh water zone) Tag @ surf
6. Install dry hole marker 8-29-02



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bingley TITLE MANAGER/SUNSET DATE 8-29-02

Type or print name Jimmy Bingley Telephone No. 915 5208756
(This space for State use)

APPROVED BY _____ TITLE _____ DATE DEC 13 2002
Conditions of approval, if any

GARY W WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

GWW