Submit 3 Copies

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office		OIL CONSERV	ATION DIVIS	ION			
			Box 2088				
DISTRICT		Santa Fe, No	ew Mexico 87504	2088			
P. O. Box 1980, Hobbs, NM 88240						OCD on New Wells)	
OISTRICT II P.O. Drawer Dd, Artesia, NM 88210					30-025-22821		
DISTRICT III					5. Indicate Type of L	8258	
1000 Rio Brazos Rd., Aztec, Nm 87410						STATE X	FEE
					6. State Oil & Gas L	ease No.	
SUNDRY NOTICES AND REPORTS ON WELLS							
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT		
(FORM C-101) FOR SUCH PROPOSALS.)							
1. Type of Well:					1		
OIL	GAS	¬					
MEIT X	WELL	OTHER			Q Mail No		
2. Name of Operator CHEVRON U.S.A. INC.					8. Well No. 101		
3. Address of Operator					9. Pool name or Wildcat		
P.O. BOX 1150 ATTN: P.R. MATTHEWS					ARROWHEAD GRAYBURG		
4. Well Location Unit Letter B		: 660' Feet From	The NORTH	Line and	1650'	Feet From The	EAST Line
Section	25	Township	21 SOUTH	Range	36 EAST	NMPM	LEA County
		10. Eleva	tion(Show whether DF, RKB,	AT, SR, etc.)			
			3518 GL				
Check Appropriets Box to Indecate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK	F	ND ABANDON	REMEDIAL WORK	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	7	ALTER CASING	
TEMPORARILY ABANDON	CHANGE		COMMENCE DRILLING	IPNS	┪	PLUG AND ABAN.	H
PULL OR ALTER CASING	H		CASING TEST AND CM	-	┪		
	D GRAYBURG PERFS	X	OTHER:	_	_		
- Table							
12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including							
esticated date of starting any processed work) SEE RULE 1103.							
CHEVRON PROPOSE	S TO CLEAN OUT AND AD	IN GRAYRURG PERES					
CHEVRON PROPOSES TO CLEAN OUT AND ADD GRAYBURG PERFS. THIS WELL WAS THE FORMER CHEVRON GRAHAM STATE (NCT·J) #1 WELL.							
MIRU, PERFORATE GRABURG ZONES 1-5 AND FRAC TREAT.							
PRESSURE TEST CA		Jimo mem					
		TAL HOLES WITH 3 1/	8" GUNS. 2 JHPF A	Г 180 DEG. PH.	ASING.		
PERFORATIONS WILL BE 2684'-3770', 32 TOTAL HOLES WITH 3 1/8" GUNS, 2 JHPF AT 180 DEG. PHASING. SWAB TEST OIL AND PUT ON PRODUCTION.							
I hereby certify that the information agove is true and complete to the best of my knowledge and belief.						4/07/05	
SI GNI TURE	P.R. Matthew	TITLE	TECHNICAL AS	SISTANT	DATE:	4/27/95	
TYPE OR PRINT NAME	P.R. M	MATTHEWS			TELEPHONE NO.	(915) 687-795	0
	ORIGINAL SIGN	ED BY					
ADDROVED DV	GARY WIN	K ,,,,			DATE	MAY 1	0 1995
APPROVED BY CONDITIONS OF APPROVAL, I	FANY: FIELD REP.	. #					