

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Hanson Oil Corporation	8. Farm or Lease Name Kingwood
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>1780</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>21-S</u> RANGE <u>36-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Blinebry-Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3546.4 G.L. 3556.4 K.B.	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is planned to re-treat Blinebry perforations 5534-5543' as follows:

1. Sand-water frac. all perforations with 2000 fals 15% acid, 60,000 gals. gelled brine water, and 90,000# 20-40 sand.
2. Swab test.
3. Put well back on pump.

Approximate date work will commence: June 28, 1972

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gerald E. Harrington TITLE Geologist DATE 6-2-72

APPROVED BY John Runyan TITLE Geologist DATE JUL 26 1972
CONDITIONS OF APPROVAL, IF ANY: