

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-23953
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name L. G. WARLICK
Well No. 3
Pool name or Wildcat BLINEBRY, DRINKARD, PENROSE SKELLY

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1 Type of Well:
OIL WELL GAS WELL OTHER

2 Name of Operator
TITAN RESOURCES I, INC.

3 Address of Operator
500 W. TEXAS, STE 500, MIDLAND, TEXAS 79701

4 Well Location
Unit Letter P 660 Feet From The SOUTH Line and 330 Feet From The EAST Line
Section 18 Township 21S Range 37E NMPM LEA County

10 Elevation (Show whether DF, RKB, RT, GR, etc.)
3498' GR

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TREAT FOR SCALE <input checked="" type="checkbox"/>

12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4/14/98 MIRU, POH w/pump & rods. Install BOP. POH w/tbg.
- 4/19/98 RIH w/rbp & pkr, set rbp @ 5914'. Test rbp to 3000 psi. PU & set pkr @ 5457'.
- 4/21/98 Pump 600 gals scale converter. SION.
- 4/22/98 Swab back load. Acidize Blinebry perfs 5576-5873' w/2000 gallons.
- 4/23/98 Swab back load.
- 4/24/98 Squeeze Blinebry w/110 gals scale inhibitor. SION.
- 4/25/98 Release pkr & rbp.
- 4/25/98 Re-set rbp @ 3850'. Test rbp to 3000 psi. Set pkr @ 3652'.
- 4/25/98 Pump 110 gals scale converter. SION.
- 4/28/98 Acidize Penrose Skelly 3723-84' w/1000 gals.
- 4/29/98 Squeeze Penrose Skelly w/110 gals scale inhibitor. SION.
- 5/1/98 Return well to production.

*1-19-98
2-19-98
3-19-98
4-19-98*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley Melton TITLE Engineering Tech DATE 07-27-98

TYPE OR PRINT NAME Shirley Melton TELEPHONE NO. (915)498-8604

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 03 1998