		r)		
NO. OF COPIES REC	EIVED										
DISTRIBUTI	ON				NEW MEXICO	OIL CONS	ERVATION CO	DMMISSIC		Form C-10	
SANTA FE										Revised 1-	
FILE											nte Type of Lease
U.S.G.S.										-	FEE 📻
LAND OFFICE										.5, State O	il & Ĝas Leas e No.
OPERATOR											
		.									
ÁP	PLICAT	TION	FOR	PERM	IT TO DRILL,	DEEPEN	, OR PLUG E	BACK		//////	
1a. Type of Work										7. Unit Ad	greement Name
		r1			00000			DLL C			
b. Type of Well	DRILL	[]			DEEPS	N SA		PLUG	БАСК	8. Farm or	Lease Name
OIL WELL VY	GAS Well			OTHER			SINGLE ZONE	м	ZONE	W. A.	Ramsay (NCT-B)
2. Name of Operator										9. Well No	D.
Gulf Oil Co	rnorat	- 1 or								6	
3. Address of Opera	itor	_101	<u> </u>							10. Field and Pool, or Wildcat	
Box 670, Hobbs, New Mexico 88240 4. Location of Well He Location 2310 FEET FROM THE NOTTH LINE						Drinkard					
4. Location of Well	nns, n	lew.	Hex.	<u>reu ac</u>	1240	2220	···· ····	Nort	L	11111	
I. Doodton of non	UNIT LE	ETTER		<u>H</u>	LOCATED	2310	FEET FROM THE	NOTE	LINE LINE	//////	
				. .		25	21 6	26	E.		
AND 430	FEET FR	TMOF	HE	East	LINE OF SEC.		TWP. 21-S	RGE.36	-E NMPM	12. Count	, , , , , , , , , , , , , , , , , , ,
AIIIIIIIIIA	11111	())	////	/////			////////	IIIII			·
$\forall IIIIIII$	71111	\overline{m}	777.	\overline{m}	MMMM	TTTTT	111111	77777	7111111	Lea	<i>4444444</i>
	/////	///	////	1111		//////		/////			
ΔΙΙΙΙΙΙΙ		$\prime\prime\prime\prime$	////	/////		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		11111	///////	/////	
XIIIIIIII	$\pi\pi\pi$	111	π	$\overline{\Pi}$		IIIII	19. Proposed I	Depth	19A. Formatio	n	20. Rotary or C.T.
		111,	////	IIII		///////	6800'		Drinkar	ď	Reverse Unit
21. Elevations (Sho	w whether	DF, I	T, etc	.) 2	IA. Kind & Status	Plug. Bond	21B. Drilling (Contractor		22. App	rox. Date Work will start
3520' GL					Blanket					Apri	1 1, 1976
23.	<u> </u>						· · · · · · · · · · · · · · · · · · ·				
					PROPOSE	D CASING A	ND CEMENT PP	ROGRAM			

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
11"	8-5/8"	241	1255'	400 sacks (Cir	culated)
7-7/8"	5-1/2"	14 & 17#	5950'	560 sacks (TOC	at 2150').
			•		
				1	l

Plans have been made to deepen and complete in Drinkard as follows: Pull producing equipment. Squeeze Blinebry perforations 5513' to 5693' with 50 sacks of Class C cement. WOC 18 hours. Test casing with 500#, 30 minutes. Drill 4-3/4" hole from total depth at 5950' to approximately 6800'. Run approximately 950'of 4" OD 11.34# K-55 casing and set at 6800' with top at 5850'. Cement liner with 75 sacks of Class H cement. WOC 24 hours. Clean out and test liner with 4000#, 30 minutes. Perforate Drinkard zone in liner with 4, 1/2" JHPF in the approximate interval 6500' to 6730'. Run treating equipment and treat new perforations with 2,000 gallons of 15% NE acid and frac with 30,000 gallons of gel brine containing 0 to 2# SPG. Flush with gel brine. Pull treating equipment. Run 4" packer on 2-3/8" tubing and set packer at approximately 5900'. Swab and clean up and place well on production.

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS	TO DEEPEN OR PLUG BACK	K, GIVE DATA ON PRESENT	PRODUCTIVE ZONE AND I	PROPOSED NEW PRODUC
TIVE ZONE, GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.				

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed C. R. Kongelsun	Title Project Petroleum Engineer	Date March 19, 1976
(This space for State Use)		All and we and it
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		



.