

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. Name of Operator GULF OIL CORPORATION</p>		<p>5. State Oil & Gas Lease No. B-1732</p>
<p>2. Address of Operator P. O. Box 670, Hobbs, New Mexico 88240</p>		<p>7. Unit Agreement Name</p>
<p>3. Location of Well UNIT LETTER G 1650 FEET FROM THE North LINE AND 2013 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 21-S RANGE 36-E N.M.P.M.</p>		<p>8. Farm or Lease Name Harry Leonard NCT-C</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3498' GR</p>		<p>9. Well No. 15</p>
<p>12. County Lea</p>		<p>10. Field and Pool, or Wildcat Blinebry & Drinkard</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p>		<p>SUBSEQUENT REPORT OF:</p>	
<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p>
<p>TEMPORARILY ABANDON <input type="checkbox"/></p>	<p>CHANGE PLANS <input type="checkbox"/></p>	<p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p>	<p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>
<p>PULL OR ALTER CASING <input type="checkbox"/></p>	<p>OTHER <input type="checkbox"/></p>	<p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p>	<p>OTHER Abandon Blinebry Perfs <input checked="" type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6734' PB.

Pull producing equipment. Set RBP @ 5775'. Spotted 2 sacks of sand on BP. Had 12' fill on top of BP after spotting sand. Squeeze Blinebry perfs 5552' - 5738' with 75 sacks of Class "C" cement. Cleaned out & tested squeezed perfs with 200# pressure for 30 minutes, held o.k. Retrieved BP. Ran tbg, rods & pump. Return well to production 6-3-78.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Norlon P. Sikes, Jr. TITLE Area Engineer DATE 6-8-78

APPROVED BY _____ TITLE _____ DATE JUN 12 1978

CONDITIONS OF APPROVAL _____