

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
J.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR NOTICES TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PURPOSES.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Gulf Oil Corporation

Address of Operator
P. O. Box 670, Hobbs, NM 88240

Location of Well
UNIT LETTER G 1650 FEET FROM THE North LINE AND 2013 FEET FROM
THE East LINE, SECTION 36 TOWNSHIP 21S RANGE 36E NMPM.

13. Elevation (Show whether DF, RT, GR, etc.)
3498' GL

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-1732

7. Unit Agreement Name

6. Form of Lease Name
Harry Leonard (NCT-C)

9. Well No.
15

10. Field and Pool, or Wildcat
Blinebry & Drinkard

12. County
Lea

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
OTHER <u>Abandon Blinebry zone</u> ☐		OTHER ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6734' PB. Set a RBP at 5775' and cap with 20' frac sand. Spot a 50 sack Class C cement plug at 5738'. Load hole with 8.6# kill fluid. Squeeze Blinebry perfs 5552-5738' and WOC. Circ and clean hole. Return Drinkard zone to production

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. B. Sikes, Jr. TITLE Area Engineer DATE 5-8-78

ORIG. SIGNED BY Jerry Sexton TITLE Dist 1, Supv. DATE MAY 9 1978

CONDITIONS OF APPROVAL, IF ANY: