

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
ROOSEVELT DISTRICT OFFICE

July 21, 1986

POST OFFICE BOX 1001
- 1986 NEW MEXICO LEGAL
ECS/10/10/86

Texas Crude Oil Company
503 Wall Towers East
Midland, Texas 79701

Re: Kincheloe 2 State #1, 2-21-36

Gentlemen:

According to the provisions of Division Order R-7766, concerning the Eunice Monument South Unit Waterflood project, all wells in the area of review are required to have sufficient cement to shut off the Eumont zone.

Our records indicate that the above referenced well does not meet these specifications.

You may run a cement bond log to confirm the top of cement if you feel the cement is now sufficient for this purpose. If the cement is not sufficient to cover the Eumont zone, you will need to perforate above the top of the cement, and squeeze sufficient cement to bring this well into compliance with Order R-7766.

We request the necessary work be completed by November 1, 1986.

Very truly yours

OIL CONSERVATION DIVISION



Jerry Sexton
Supervisor, District I

JS:bp

cc: R. L. Stamets
Chevron U.S.A. Inc.
File

*Recompletion, well completion & cementing
Requirements*