

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator <b>SOHIO PETROLEUM COMPANY</b>		8. Farm or Lease Name <b>Alves</b>	
3. Address of Operator <b>P.O. Box 3167, Midland, Texas 79701</b>		9. Well No. <b>3</b>	
4. Location of Well UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>18</b> TOWNSHIP <b>21S</b> RANGE <b>37E</b> NMPM.		10. Field and Pool, or Wildcat <b>Eunice, N. (San Andres) Gas</b>	
15. Elevation (Show whether DF, RT, GK, etc.) <b>3489 KB, 3473 G.L.</b>		12. County <b>Lea</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug back to 4075' w/Permanent packer and expendable plug, isolating perforations 4085-4118. Perforate selectively w/one shot each at 4026, 4028, 4031, 4034, 4037, 4041, 4044, & 4046. Acidize w/200 gal. 15% NE acid, swab back, and acidize w/750 gal. 15% NE acid if necessary to make a commercial gas well. Proposed perforations are still within the San Andres formation.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Burton Whiteley TITLE District Superintendent DATE June 26, 1973

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

\_\_\_\_\_

---