

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

** State Lease Numbers B-6717-4,
B-1167-3 & 5, B-6807-2, B-8521-2

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. **	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Dorchester Exploration, Inc.		8. Farm or Lease Name Wilson State Comm.
3. Address of Operator 1100 Midland National Bank Tower, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER I, 1980 FEET FROM THE South LINE AND 990 FEET FROM East LINE, SECTION 13 TOWNSHIP 21-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat Wilson (Strawn)
15. Elevation (Show whether DF, RT, GR, etc.) 3651' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to cut off 5-1/2" casing at approximately 10,200'. TD is 12,591' with 5-1/2" casing set at 12,416'. PBTD is 11,965'. Cement plugs will be set as follows:

CIPB set at 11,100' with 35' cement on top of plug. THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE THE PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.
100' cement plug 1/2 in and 1/2 out of 5-1/2" stub.
100' cement plug 5555' up to 5455".
100' cement plug 1/2 in and 1/2 out of 9-5/8" stub or at base of salt.
100' cement plug 1/2 in and 1/2 out of 13-3/8" set @ 510".

10 sock plug at surface with 4" steel marker.

IF 5 1/2 IS PULLED FROM BELOW 6000' GIVE OGD A CALL FOR ADDITIONAL PLUGS

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lynn Austin TITLE Division Superintendent DATE June 1, 1979
APPROVED BY Jerry Sexton TITLE Dist 1, Supv. DATE JUN 4 1979
CONDITIONS OF APPROVAL, IF ANY: