Harist voller hims band					
DISTRIBUTION BANTA FE	P. O. BOX 2088 ANTA FE SANTA FE, NEW MEXICO 87501			Form C-103 Revised 19-1-1	
U.S.O.S. LAND OFFICE OPERATOR				State X Fee State Oil 6 Gas Lease No.	
				K 5389	~~
SUI DO NOT USE THIS FORM FO	NDRY NOTICES AND REAL PROPOSALS TO DRILL OR TO DE LICATION FOR PERMIT - " (FORM	PORISON WELLS EPEN OR PLUG BACK TO A DII C-101) FOR SUCH PROPOSALS	FFERENT RESERVOIR. S.)]]]
I. OIL CAS WELL X	OTHER-			7. Unit Agreement Name	
2. Nome of Operator Hunt Industries				8. Farm or Lease Name State '15'	-
3. Address of Operator 600 W. Illinois	Suite 706 Mid	lland, Tx 7970	1	9. Well No.	
4. Location of Well	1980 TEET FROM THE			10. Field and Pool, or Wildcat South Osudo	
	15 TOWN			XIIIIIIIIII	
15. Elevation (Show whether DF, RT, GR, etc.) GR 3589				12. County Lea	
Che	ck Appropriate Box To F INTENTION TO:	Indicate Nature of	•	ther Data	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND Change P		WORK DRILLING OPMS. ST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT	
OTHER		OTHER.		•	-
17. Describe Proposed or Complete work) SEE RULE 1103.	ed Operations (Clearly state a	Il pertinent details, and giv	e pertinent dates, includir	g estimated date of starting any prop	105 €1
See attached for	r plugging procε	dure.			
		•			

18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Production Foreman DATE 11-3-88

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT | SUPERVISOR

TITLE Production Foreman DATE 11-3-88

CONDITIONS OF APPROVAL, IF ANY: