MCVAY DRILLING COMPANY

308 PHILTOWER

TULSA, OKLAHOMA 74163

C. R. McVay J. C. McVay TULS CT TO STORY IS LUC LUC TY THOMAS THE RESULT OF THE RE

November 17, 1976

Mr. Arthur Brown
U.S.G.S.
Box 1157
Hobbs, New Mexico 88240

Dear Sir:

Please find enclosed, the diagram for our Blow Out Preventor stack for the production string on the Belco-Federal 12 #1. The Blow Out Preventor stack for the intermediate casing will be the same with the exception that we will not run a hydril, and it will be a 12" 900 series. Please note that the fill up connection will be above the Blow Out Preventors. Also note in the asterisk #1 and #2, that we will run an extra hydraulic valve under asterisk #1, and a manual valve under asterisk #2. We will also use a Rotating Stripper Head below the intermediate casing, and an upper and lower Kellycock valve at all times.

If I can be of any further assistance to you, please don't hesitate to call.

Yours truly,

MCVAY DRILLING COMPANY

Jim McVay

dn/jm Enclosure