

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. L-922	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-		7. Unit Agreement Name
2. Name of Operator Pogo Producing Company		8. Farm or Lease Name State L-922
3. Address of Operator P.O. Box 10340 Midland, Texas 79702		9. Well No. 2
4. Location of Well UNIT LETTER <u>J</u> <u>1780</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>21-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat Undesignated
11. Elevation (Show whether DF, RT, GR, etc.) 3726' GR, 3743' KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
OTHER _____		OTHER <u>Plug & abandon Pennsylvanian</u> & completion in Wolfcamp	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/1/86
McCullough RIH 5" CIBP on W.L. & set @ 12,250'. McCullough RIH 5" Howco "EZ" drill cmt retainer on WL & set 12,150'.

2/2/86
Set Howco stinger in S.V. cmt retainer establish injection rate @ 2 BPM w/3000#, Howco sqz cmt perfs @ 12,169'-12,176' w/100 sxs Cl H. Pumped 89 sxs into perfs w/5300#, Max sqz press. Pull stinger to 12,140' Rev out 9 sxs cmt left 10' cmt on top of retainer.

2/4/86
McCullough perf 5" liner & 7" csg w/3 3/8" csg gun 2 JSPF 12,106'-12,112'. RIH Howco 5" RTTS pkr on 2 7/8" & 2 3/8" tbq & swab test formation.

2/6/86
McCullough ran Howco cmt retainer on WL & set 12,095'. RIH Howco cmt retainer stinger to cmt ret @ 12,095' on 2 7/8" & 2 3/8" tbq.

2/7/86
Howco cmt sqz perfs 12,106'-12,112' w/100 sxs Cl H cmt. Spot 10' cmt on top ret to 12,085'.

CONTINUED ON ATTACHED SHEET.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>2/25/86</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>MAR 3 - 1986</u>