STRICT SUPERVISOR

UNITED STATES				
DEPARTMENT OF THE INTERIO	F			
GEOLOGICAL SURVEY				

Budget Bureau No. 42-R1424		
5. LEASE LC-031741(a)		
6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
7. UNIT AGREEMENT NAME NMFU		
8. FARM OR LEASE NAME Hawk A		
9. WELL NO. 7		
10. FIELD OR WILDCAT NAME Blinebry / Drinkard		
11. SEC., T., R., M., OR BLK. AND SURVEY O AREA		
Sec 8, T-215, R-37E 12. COUNTY OR PARISH 13. STATE Lea NM		
14. API NO.		
15. ELEVATIONS (SHOW DF, KDB, AND WD		

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) oil other well well 2. NAME OF OPERATOR CONOCO INC. ADDRESS OF OPERATOR, N.M. 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AT SURFACE: 990 FNL 1980 FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL MOTE: Return lesults of multiple completion or zone change on Form 9–330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES U.S. GEOLOGICAL SURVE ABANDON* HOBBS, NEW MEXICO, (other) DHC 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill out CIBP at 6197' and 6200'. Recover & POOH. CO to 6870'. GIH w/ +bg, SN. SN to 6825! Place well on production. Test.

DHC approvedunder Order No. DHC-329 issued December 4,1980.

Subsurface Safety Valve: Manu. and Ty	/pe	Set @ Ft
18. I hereby certify that the foregoing SIGNED Was 9. Butterfor		
	(This space for Federal or State office use)	APPROVED
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	DATE	JAN 1 4 1981

US455 MMF44