May 10, 1983 File: SJO-867-WF Page 2

C-116 for the Drinkard are attached.

*Blinebry is not required to be reported on C-116. Data furnished by actual well tests. Reference production decline curves.

**We do not feel this is a representative well test. The well is currently experiencing loading problems and has a column of fluid in the hole. A previous well test dated 2-7-83 is more representative of true production 12 BOPD, 0.5 BWPD, and 37 MCFD. Reference our production decline curves attached. Recovery will be enhanced by rod pump when commingled.

- 2. Neither zone produces more water than the combined oil limit as determined in Rule 303-C.
- 3. The produced fluids should be compatible and commingling these fluids should not result in precipitates which might damage the reserves.
- 4. No depreciation of value will occur from downhole commingling. The Blinebry and Drinkard production is surface commingled on the closely located McQuatters Lease without depreciation of value. (Commingling Order PC-592, dated December 3, 1980.)
- 5. Expected daily production from the commingled zones are as follows:

	Blinebry	Drinkard	Commingled
BOPD	30	15	45
BWPD	15	2	17
MCFD	30	75	105

- 6. The commingling will not jeopardize the efficiency of future secondary recovery operations in either zone.
- 7. Bottom hole pressure estimations and calculations for each zone are as follows:

Drinkard

SITP: 100 PSI
Gas Gravity: 0.85
Oil Gravity: 41° API
Estimated Fluid Level: 1500' Above Mid perfs
No water in fluid column.