

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

COPY TO O. C. C.

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME HAT MESA
2. NAME OF OPERATOR BASS ENTERPRISES PRODUCTION CO.	8. FARM OR LEASE NAME HAT MESA
3. ADDRESS OF OPERATOR Box 2760, MIDLAND, TX 79702	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) 660' FNL & 660' FWL OF SECTION - UNIT LETTER D.	10. FIELD AND POOL, OR WILDCAT UNDES. MORROW
5. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T21S-R32E
6. ELEVATIONS (Show whether DF, RT, GR, etc.) 3746' GL 3764' KB	12. COUNTY OR PARISH LEA
	13. STATE N. Mex.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

DRILLED 11" HOLE TO 5200'. RAN 5 7/8" CASING - SET @ 5160'.
DV TOOL @ 3298' - 3303'. CEMENTED WITH 350 SKS "LITE" PLUS ADDITIVES -
TAILED WITH 200 SKS CLASS "C" PLUS ADDITIVES. PLUG DOWN @ 2:00 AM
CDST OCTOBER 13, 1979. OPENED DV TOOL AFTER FOUR (4) HOURS. PUMPED
1250 SKS HALLIBURTON "LITE" PLUS ADDITIVES. PLUG DOWN @ 8:00 AM CDST
OCTOBER 13, 1979. CIRCULATED OUT 40 SKS. WOC 16 HOURS. DRILLED
DV TOOL. TESTED BOPE TO 5000' AND HYDRIL TO 1500' DRILLED FLOAT,
SHOE AND 5' FORMATION. TESTED FORMATION TO 1100' - HELD OK.
DRILLING 7 7/8" HOLE.

RECEIVED

NOV 8 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

15. I hereby certify that the foregoing is true and correct

SIGNED

H. J. Marty, Jr.

TITLE

Sr. Prod. Clerk

DATE

Nov. 6, 1979

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

NOV 08 1979

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO 68-1179

RECEIVED

NOV 13 1979

O.C.D. HOBBS, OFFICE