STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 0" CUPIZE ACCESTAD	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

MO. OF CUPICS SCCEIVED	OIL CONSERVATION DIVISION		
DISTRIBUTION	P. O. BOX 2088	Form C-103	
SANTAFE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78	
FILE			
U.S.G.S.		Sa. Indicate Type of Lease	
LAND OFFICE		State X Fon	
OPERATOR	ţ ·	5, State Oil & Gas Lease No.	
L		E-394	
		mmmmmm	
SUNDRY A	CTICES AND REPORTS ON WELLS		
USE "APPLICATION P	LS TO DRILL OR TO CEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. OR PERMIT —'* (FORM C-101) FOR SUCH PROPOSALS.)		
1.		7. Unit Agreement Name	
OIL GAS WELL T	THER.	•	
2. Name of Operator		8. Farm or Lease Name	
Amerada Hess Corporation		State WE "A"	
i. Address of Operator	Address of Operator		
Descript D. Monimont Nort	Mayrian 90265	Δ .	
Drawer D. Monument, New	MEXICO 00203	10. Field and Pool, or Wildcat	
1		10, 1 tota and 1 bot, or writed	
UNIT LETTER F , 1800	FEET FROM THE North LINE AND 1980 FEET	FROM Eumont	
**************************************	ום אור אדי		
THE WEST LINE, SECTION	12 TOWNSHIP 21S RANGE 35E	MMPM. (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
	3572' GL	Lea \\\\\\\\	
Спеск Арр	opriate Box To Indicate Nature of Notice, Report o	r Other Data	
NOTICE OF INTE	NTION TO: SUBSEQU	JENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
\equiv		i H	
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB X		
	OTHER		
OTHER			
	ons (Clearly state all pertinent details, and give pertinent dates, incl	luding estimated date of starting any proposed	
work) SEE RULE 1103.		•	
Soudded 12-1/4" hole @ 11	:15 AM 12-27-79. Drld. 12-1/4" hole to 33	2'. Set 8-5/8" csg. at 327'	
	lass C cement mixed 3% CaCl. Circ. out 10		
•			
tested w/1500# press. 1/3	0 min. Held OK. Drld. 7-7/8" hole to 343	st', circ. and conditioned	
hole and ran CN Densilog	with GR and caliper fr. 3431' to surface.	Trip in & conditioned hole.	
Trip out and ran 5-1/2"	4# csg. set at 3431', bottom 11 jts. csg.	sand blasted. Cemented w/	
	x, 6# salt & 1/4# celloflake, 6% gel & 2%		
	s. Set csg. on slips & rigged down drlg. r	ig. Rig released at 5:00 AM	
1-4-80.			
1-28-80: Rigged up pullir	g unit & trip in \(\delta/4-3/4\)" bit, DC's & 2-7/	'8" tha. Drld. float shoe	
at 22001 compat s format	ion to 3442'. Blew csg. dry w/gas, drld.	formation fr 3442! to	
	tbg., DC's & bit & ran "F" nipple w/blanki	ng prug in piace on 110	
jts. 2-3/8" tbg. Pulled	plug fr. "F" nipple and CI.		
	•		
Test of 1-31-80: Flowed o	ry gas at rate of 2348 MCFPD w/360# TP.		
	<u></u>		
		 	
18. I hereby certify that the information above	e is true and compl. ————————————————————————————————————		
6 × 2. V.	Come Adm Con	OATE 2-12-80	
SIGNED UNITED	Supv. Adm. Ser.	DATE Z-12-00	
O			
Orig. Signed by		ge	
Jerry Sexton		DATE <u>FFB 1 1980</u>	
Dist 1. Supv.			
Dist 1 Sup 1			