

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27135
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3662
7. Lease Name or Unit Agreement Name Hunt APO State
8. Well No. 1
9. Pool name or Wildcat Grama Ridge Bone Spring, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	
4. Well Location Unit Letter <u>T</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>4</u> Township <u>21S</u> Range <u>34E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3730' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Pull RBP's & acidize perfs <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-20-95 - Moved in and rigged up pulling unit. TOOH with rods and pump. Nipped down wellhead and installed BOP. Unset anchor and TOOH with production string. Shut down.

10-21-23-95 - TIH with overshot, jars, drill collars and 2-7/8" tubing. Circulated on top of RBP at 9173'. Latched onto RBP at 9173'. Tried to unset RBP - could not get any movement thru mandrel. Jarred on RBP for 1 hour. Sheared off of retrieving head. TOOH with tubing, drill collars, jars and overshot.

10-24-95 - TIH with overshot, drill collars, jars and tubing. Circulate on top of RBP at 9173'. Latched onto RBP and jarred RBP loose. TOOH with tubing, jars, drill collars, overshot & RBP. TIH with retrieving head, drill collars, jars and tubing. Circulate 12' of sand off of RBP at 9471'. Latched onto RBP at 9471' and unset RBP. TOOH with tubing, jars, drill collars, retrieving head and RBP. Shut down.

10-25-95 - TIH with packer & tubing. Set packer at 9450'. Swabbed. Rigged up slickline. Run in hole with 72 hour bottom hole pressure bomb. Running 72 hour BHP buildup.

10-27-95 - Pulled 72 hour bomb.

10-31-95 - Acidized perfs. 9556-9657' w/2500 gallons 7-1/2% NEFE acid & ball sealers.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 10-31-95
TYPE OR PRINT NAME Rusty Klein 505-748-1471
TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REPRESENTATIVE

APPROVED BY _____ TITLE _____ DATE _____

NOV 02 1995