

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-71

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.I.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
17-987

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEED OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name East Hobbs State Unit
2. Name of Operator Gulf Oil Corporation	8. Form or Lease Name
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER F, 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 21S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DE, RT, GR, etc.) 3772' GL	12. County Lee

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Lost circulation at 3995'; dry drilled to 4234'. Trip in open-ended with drill pipe to 3950'. Cement with 400 sacks thick set with 2% CaCl₂; cement on spot at 1:45 A.M., 6-18-81. Wait on cement. Drill cement 3739'-4100'. TTH with drill pipe to 3950'. Spot 200 sacks thick set with 2% CaCl₂. Wait on cement. Drill 4190'-4247'. Pipe stuck, spotted 50 barrels oil at 4225', stuck at top of drill collars; back off, left bit, SS, DC's, x-over and 1 joint drill pipe. Fish 3722'-4225', wash to top of fish, fish moved downhole, lost 150 barrels fluid. POH with bit, SS, DC's and 1 joint drill pipe. Cement plug with 400 sacks thick set with 2% CaCl₂. Washed and reamed 570'-1100'. Circulate hole at 4004'; temperature survey 3990'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED T. P. [Signature] TITLE Area Drilling Superintendent DATE 7-29-81

APPROVED BY [Signature] TITLE DATE JUL 30 1981
CONDITIONS OF APPROVAL, IF ANY: