STATE OF NEW MEXICO (ERGY AND MINERALS DEPARTMENT			_	
DISTRIBUTION BANTA FE V.S.G.S.	OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501			Form C-103 Revised 10-1-78
LAND OFFICE				State OII & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-1011 FOR SUCH PROPOSALS.)				
OIL GAS OTHER-				7. Unit Agreement Name
Alpha Twenty-One Production Company				3. Form or Lease Home Lansford
Address of Operator P.O. Box 1206, Jal, NM 88252				9. Well No. 5
Jocation of Well				0. Field and Pool, or Wildcat
UNIT LETTER J. 1650 FEET FROM THE South LINE AND 2160 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 21S RANGE 37E NMPM.				Penrose-Skelly
	15. Elevation (Show whether	DF, RT, GR, etc.)		2. County
		round Level		Lea Allili
NOTICE OF INTENTION		ature of Notice, Repo SUBS		r Data REPORT OF:
RF DAM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK Commence drilling opns.		ALTERING CASING
LL DR ALTER CABING	CHANGE PLANB	CASING TEST AND CEMENT JO		g X
OTHER				
Describe Proposed or Completed Operations (Cl work) SEE RULE 1 f03.	early state all pertinent deta	ails, and give pertinent dates	, including es	timated date of starting any proposed
The well was spudded 7-3-82.				
Drilled 15" hole and ser Redimix to surface. Drilled 12-1/2" hole and cemented with 275 sx 7-4-82) Drilled 7-7/8" hole and follows:	d set 402.67' of 8 Class "C", CACL <b>2</b> .	8-5/8" 23#, Grade Circulated 100	B Surfac sx. (Wo:	e Casing and rk accomplished
Guide Shoe		001		
Shoe joint Float Collar	• • •			
106 joints Total	<u>4238,36</u> 1 			
Cement: Lead Slurry: 850 sx Tail Slurry: 475 sx 7-11-82)			sx. (Wo:	rk accomplished
I hereby certify that the information above in the	rend complete to the best of	my knowledge and belief.	•••••••••••••••••	
" Jovest W dansfore		/Energy Resources	<u> </u>	DATE 7-12-82
ORIGINAL SIGNED BY	TITLE			JUL 10 1982
DITIONS OF APPROVDISTRICI, SUPR,				