

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

|  |  |   |  |
|--|--|---|--|
| <b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK<br>DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"<br>(FORM C-101) FOR SUCH PROPOSALS.)   |  | API NO. (assigned by OCD on New Wells)<br><b>30-025-29093</b>   |  |
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>  |  | 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>   |  |
| 2. Name of Operator<br><b>CHEVRON U.S.A. INC.</b>  |  | 6. State Oil & Gas Lease No.<br><b>N/A</b>  |  |
| 3. Address of Operator<br><b>P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE</b>   |  | 7. Lease Name or Unit Agreement Name<br><b>ARROWHEAD GRAYBURG UNIT</b>  |  |
| 4. Well Location<br>Unit Letter <b>D</b> : <b>660</b> Feet From The <b>NORTH</b> Line and <b>990</b> Feet From The <b>WEST</b> Line<br>Section <b>36</b> Township <b>21 SOUTH</b> Range <b>36E</b> NMPM <b>LEA</b> County  |  | 8. Well No.<br><b>120</b>   |  |
| 10. Elevation(Show whether DF, RKB, RT, GR, etc.)<br><b>3519' GL</b>   |  | 9. Pool name or Wildcat<br><b>ARROWHEAD GRAYBURG</b>  |  |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  |  |   |  |
| <b>NOTICE OF INTENTION TO:</b><br>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/><br>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/><br>PULL OR ALTER CASING <input type="checkbox"/><br>OTHER: <b>CO, PERF &amp; ACDZ</b> <input checked="" type="checkbox"/> |  | <b>SUBSEQUENT REPORT OF:</b><br>REMEDIAL WORK <input type="checkbox"/> ALTER CASING <input type="checkbox"/><br>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABAN. <input type="checkbox"/><br>CASING TEST AND CMT JOB <input type="checkbox"/><br>OTHER: <input type="checkbox"/> |  |

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO: MIRU. ND WH, NU BOPE. CLEAN OUT TO PBTD. RUN GR/CCL/USIT LOG  
F/4091'-3400'. SET RBP AND PKR AND CHECK FOR FLUID ENTRY AND OIL CUT.  
RIH W/BIT AND CLEAN OUT TO 4091'. PERF W/2 JHPF @3675'-78',3684'-86',3830'-32',  
3858'-61',3870'-73'. ACDZ EACH SET W/2 BBLs ACID. SWAB BACK.  
RIH W/TBG. ND BOPE. NU WH. TURN WELL OVER TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Wendy Kingston* TITLE TECH. ASSISTANT DATE: 05/9/94  
TYPE OR PRINT NAME WENDY KINGSTON TELEPHONE NO. (915)687-7436

APPROVED BY *Paul Kautz* TITLE Geologist DATE MAY 11 1994  
CONDITIONS OF APPROVAL, IF ANY: