

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 221
9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTOR
2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)
4. Well Location Unit Letter 0 : 2983 Feet From The SOUTH Line and 2317 Feet From The EAST Line Section 2 Township 21S Range 37E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3499' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: CTI (ORDER #R-B541) ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-15 to 3-21-89:

POH w/prod equip. CO to 6916'. Set pkr @ 5763' & tstd csg to 500#, held OK. TOH w/pkr. Installed inj equip, setting Guib Uni-VI pkr @ 5760'. Pres tstd csg to 500#, held OK.

5-09-89:

Commenced inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 7-11-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUL 14 1989

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 221
9. Pool name or Wildcat NORTH TUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator SHELL WESTERN E & P INC. (4431 WCK)
3. Address of Operator P.O. BOX 576, Houston, TX 77001-0576	4. Well Location Unit Letter 0 : 2983 Feet From The South Line and 2317 Feet From The East Line Section 2 Township 21-S Range 37-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3499' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: CTI ☒	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) POOH w/ prod equip.
- 2) CO to 6900'.
- 3) Pres test to 300 psi, using pkr set @ 5750'.
- 4) TIH w/ inj equip, setting Guiberson Uni-VI pkr @ 5750'.
- 5) Pres test to 300 psi for 30 min.
- 6) Tie into inj system and place well on injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE 3/15/89
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE **MAR 21 1989**
CONDITIONS OF APPROVAL, IF ANY:

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103.
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. GIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 221
4. Location of Well UNIT LETTER 0, 2983 FEET FROM THE SOUTH LINE AND 2317 FEET FROM THE EAST LINE, SECTION 2, TOWNSHIP 21S, RANGE 37E, N.M.P.M.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS
11. Elevation (Show whether DF, RT, GR, etc.) 3499' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
OTHER ☐		Log, Zone Tstd Tubb, OAP & Acd ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-06 to 6-10-88:

POH w/prod equip. Ran SDT, CNL, GST, NGT & CET/CBL logs. Perf'd Tubb 6230' - 50' (1 JSPF). Set RBP @ 6430'. Acd perfs 6230' - 50' w/3150 gals 15% HCl-NEA. Installed prod equip & ret'd well to prod for Tubb zone tst.

7-06 to 7-13-88:

POH w/prod equip & RBP. Perf'd Blinebry/Tubb/Drinkard 5861' - 6833' (1 JSPF). Set RBP @ 6871'. Acd Tubb/Drinkard perfs 6475' - 6850' w/7140 gals 15% HCl + 1500# rock salt. POH w/RBP. Set RBP @ 6460'. Acd Tubb perfs 6374' - 6411' w/2100 gals 15% HCl-NEA. Rel RBP & reset @ 6220'. Acd Blinebry perfs 6015' - 6176' w/2100 gals 15% HCl. Acd Blinebry perfs 5797' - 6176' w/5208 gals 15% HCl + 1000# rock salt. Rel RBP & POH. Installed prod equip & ret'd well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 7-19-88

ORIGINAL FILED IN 100-100000-1000

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103.
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 221
4. Location of Well UNIT LETTER <u>0</u> , <u>2983</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>2317</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>2</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool or Wildcat NORTH EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS
15. Elevation (Show whether DF, RT, GR, etc.) 3499' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>LOG, ZONE TST TUBB, OAP & ACDZ</u> ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. Run the following cased hole logs: SDT, CNL, GST, NGT, CET/CBL.
3. Perf Tubb 6230'-50' (1 JSPF).
4. Set RBP @ 6500'.
5. Acdz perfs 6230'-50' w/3150 gals 15% HCl-NEA.
6. Install prod equip & return well to prod for Tubb zone tst.
7. POH w/prod equip & RBP.
8. Perf Blinebry/Tubb/Drinkard 5914' - 6833' (1 JSPF).
9. Acdz perfs 5914' - 6850' w/17,850 gals 15% HCl-NEA + 1500# rock salt using RBP & pkr.
10. TOH w/RBP & pkr.
11. Install prod equip & return well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 5-17-88

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE MAY 20 1988

CONDITIONS OF APPROVAL, IF ANY: