

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-

30. Indicate Type of Lease
State ☒ Fee ☐
3. Since Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO SPECIAL CO PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Chevron U.S.A. Inc.
3. Address of Operator
P. O. Box 670, Hobbs, NM 88240
4. Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 2080 FEET FROM
THE East LINE, SECTION 22 TOWNSHIP 21S RANGE 36E
15. Elevation (Show whether DF, RT, GR, etc.)
3596.7 GL
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7 7/8" hole @ 4051'. Logged well. Ld DP & DC. RU and ran 99 joints
5 1/2" 15.5# K-55 LT&C set @ 4051'. Cemented with 350 sacks class "C" .6% D-60
.2% D-46 1/2#/sack D-29 1#/sack J-51. Plug down 10:40 am 9-29-1985. Tested
casing to 1500psi. Top of cement from temperature survey @ 2000'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Jerry Sexton Division Drilling Manager 10-1-1985
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR
OCT 4 - 1985