

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2686
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease State ☒ Fee ☐	
5. State Oil & Gas Lease No. V-1902	
7. Unit Agreement Name	
8. Name of Lease State Chilkat State 6	
9. Well No.	
10. Field and Pool, or Wildcat Wilson y-SR	
12. County Lea	

SUMMARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEVELOP A WELL IN A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL FORM 1001 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Happy Oil Company/Chilkat, Inc.
3. Address of Operator P.O. Box 343 Artesia, N.M. 88210
4. Location of Well UNIT LETTER W 330' FEET FROM THE S LINE AND 1650' FEET FROM THE E LINE, SECTION 6 TOWNSHIP 21S RANGE 35E N.M.P.M.

15. Elevation (Show whether SF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposals or Complicated Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot acid-Pull TB6 & perforate -Run Pwr. Break down & Acidize w/22 bbls acid & 20 balls .
Flush w/2% KOL H₂O.

casing perforations size .40 holes per foot - intervals 3734-3744 (10 holes)
15% SRA Acid.

20 ball sealers in 10 stages of 2.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dennis Klout TITLE Office Manager DATE 8-18-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

AUG 31 1987