

NO. OF COPIES RECEIVED	
DISTRIBUTION	
AREA FE	
LE	
S.A.S.	
NO OFFICE	
PERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

☐ GAS WELL ☐ OTHER- <u>WSW</u>		7. Unit Agreement Name
1. Operator		Eunice Monument South Unit
Chevron U.S.A. Inc.		8. Farm or Lease Name
		Eunice Monument South Unit
2. Address of Operator		9. Well No.
P. O. Box 670, Hobbs, NM 88240		459
3. Location of Well		10. Field and Pool, or Wildcat
LETTER <u>B</u> ¹⁰⁷⁰ 1420 FEET FROM THE <u>South</u> LINE AND ¹⁷⁴⁰ 1270 FEET FROM <u>East</u> LINE, SECTION <u>#5</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> N.M.P.M.		Eunice Monument G-SA
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

☐ REMEDIAL WORK ☐ FULLY ABANDON ☐ ALTER CASING ☐ PLUG AND ABANDON ☐ CHANGE PLANS ☐	☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPS. ☐ CASING TEST AND CEMENT JOBS ☒ OTHER <u>inspected for csg risers to surf</u>	☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☒
---	--	--

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations) SEE RULE 1103.

Risers have been inspected by OCD personnel.

by certify that the information above is true and complete to the best of my knowledge and belief.		
<u>Jerry Sexton</u>	TITLE <u>New Mexico Area Supt.</u>	DATE <u>2-21-87</u>
ORIGINAL SIGNED BY JERRY SEXTON		
DISTRICT I SUPERVISOR	TITLE	DATE <u>MAR 1 1987</u>
OTHERS OF APPROVAL, IF ANY:		