

DISTRIBUTION		
ANTA FE		
ICE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

P. O. BOX 2088
SA. TA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL ☐ GAS WELL ☐ OTHER- <u>WIW</u> 2. Name of Operator <u>Chevron U.S.A. Inc.</u> 3. Address of Operator <u>P. O. Box 670, Hobbs, NM 88240</u> 4. Location of Well 5. LETTER <u>P</u> <u>660</u> <u>659</u> FEET FROM THE <u>South</u> LINE AND <u>to 560</u> FEET FROM <u>Coast</u> LINE, SECTION <u>10</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> N.M.P.M. 6. <u>Coast</u> LINE, SECTION <u>10</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> N.M.P.M.	7. Unit Agreement Name <u>Eunice Monument South Unit</u> 8. Farm or Lease Name 9. Well No. <u>346</u> 10. Field and Pool, or Wildcat <u>Eunice Monument G-SA</u>
11. Elevation (Show whether DF, RT, GR, etc.) 12. County <u>Lea</u>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

1. REMEDIAL WORK ☐ 2. PARTIALLY ABANDON ☐ 3. ALTER CASING ☐ 4. ☐	5. PLUG AND ABANDON ☐ 6. CHANGE PLANS ☐ 7. ☐	8. REMEDIAL WORK ☐ 9. COMMENCE DRILLING OPS. ☐ 10. CASING TEST AND CEMENT JOBS ☐ 11. OTHER <u>commence water injection</u> ☒	12. ALTERING CASING ☐ 13. PLUG AND ABANDONMENT ☐ 14. ☐
---	---	--	---

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Began water injection 8-28-87
Injection Sucking Pressure 0
Daily Injection Rate 720 u/bbls

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Eddie W. Seay TITLE New Mexico Area Supt. DATE 8-28-87

ED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE SEP 8 1987

CTIONS OF APPROVAL, IF ANY: